

5 BLM

1 File

1 Andes

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. Gallup, Dakota

OIL WELL ☒ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Dugan Production Corp.

3. ADDRESS OF OPERATOR

P O Box 208, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

790' FWL - 1650' FSL

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

6677' GL

5. LEASE DESIGNATION AND SERIAL NO.

NM-10089

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Mary Anne

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Bisti Gallup/Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec.9, T24N, R9W, NMPM

12. COUNTY OR PARISH

San Juan

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Plug Back

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

4-8-85 M.I.& R.U. unit and pull rods and tubing. Set cast iron bridge plug
thru at 6278' on wireline and dumped 50' cement on top of bridge plug.
4-10-85 New P.B.T.D = 6228'. Reran tubing & rods. Landed tubing at 5366'
FKB, with seating nipple at 5329'. N.D. BOP. N.U. wellhead and
returned well to production.

Dakota perfs abandoned below CIBP and Gallup perfs open to production
as of 4-9-85.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jim L. Jacobs

TITLE

Geologist

DATE 4-12-85

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE APR 17 1985

FARMINGTON RESOURCE AREA

BY Smm

*See Instructions on Reverse Side

NMOC