

Form 3160-5  
(June 1990)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTFORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

NOO-C-14-20- 8452

6. If Indian, Allottee or Tribe Name

Navajo

7. If Unit or CA, Agreement Designation

8. Well Name and No.

South Blanco Navajo 25#1

9. API Well No.

30 045 25064

10. Field and Pool, or Exploratory Area

Lybrook Gallup

11. County or Parish, State

San Juan County, NM

## SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other P&A

2. Name of Operator

Dugan Production Corp.

3. Address and Telephone No.

P.O. Box 420, Farmington, NM 87499 (505) 325-1821

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FSL & 950' FEL (SE/4 SE/4)  
Unit P, Sec. 25, T24N, R8W

## 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

## TYPE OF ACTION

☒ Abandonment☐ Recompletion☐ Plugging Back☐ Casing Repair☐ Altering Casing☐ Other☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut-Off☐ Conversion to Injection☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well was plugged as follows:

- 1.) Set a CIBP @ 5291'. Spotted an 8 sk class B plug on top.
- 2.) Pulled up to 3510'. Spotted a 12 sk class B plug inside casing. Top of plug 3360'.
- 3.) Pulled up to 2048'. Spotted a 65 sk class B plug inside casing. Top of plug 1432'.  
1206
- 4.) Pulled up to 297'. Filled casing full to surface with 35 sks cement.
- 5.) Cut off wellhead and set dry hole marker.

14. I hereby certify that the foregoing is true and correct

Signed Gary Brink  
(This space for Federal or State office use)Title Operations ManagerDate 3/12/96Approved by \_\_\_\_\_  
Conditions of approval, if any:

Title \_\_\_\_\_

Date \_\_\_\_\_