Rig up Geosource. Set 4½" Baker bridge plug at 6145'. Dump 4-27-82 50' cement on top of Bridge plug with dump bailer. Perforate Gallup Formation 5268-80 (12 holes). Rig up Western Co. Break down perfs with water at 1800 psi. Perforate at follows: 5340-48 (8 holes), 5306-12 (6 holes), 5244-50 (3 holes), 5228-36 (4 holes), 5184-94 (5 holes), 5156-70 (7 holes), 5132-38 (3 holes). Total 48 holes.

Fraced Gallup formation as follows:

Spearhead 500 gals 15% HCL 5000 gal slickwater - pad 75,000 gal slick water + 1#/gal 20-40 sand Flush to top perf.

ISDP 1350 psi 15 min shut in 1000 psi Max treating press 3500 psi Min treating press 1550 psi Ave treating press 2000 psi at 36 BPM

Dropped 25 RCN ball sealers. Had good ball action.

Totals: 75,000# 20-40 sand 83,402 gal slick water 80 gal. Aquaflow

200# FR-2

Shut well in over night.

Opened well up. Went in hole with tbg. Tagged sand at 5950'. Landed tbg. as follows: 168 jts. 2-3/8" 0.D., 4.7#, N80, 8RD, EUE tbg. with modified couplings. T.E. 5325.80' set at 5334' RKB. Seating nipple at 5298' with mud anchor below it. Well flowed 4-28-82 back while running tbg. N.D. BOP. N.U. well head. Swab tbg. for 3½ hrs. Fluid staying about 300-400' from surface. Rig down MTK. Shut well in.

Form 9–331 5 USGS Dec. 1973	2 Wexpro	l File	Form Appr Budget Bu	roved. Freau No. 42–R1424
UNITED ST	TATES	5. LEASE		
DEPARTMENT OF THE INTERIOR		NM 16760		
GEOLOGICAL			, ALLOTTEE OR	TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)		7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME		
2. NAME OF OPERATOR DUGAN PRODUCTION CO	#4 10. FIELD OR	WILDCAT NAME	 E	
3. ADDRESS OF OPERATOR P 0 Box 208, Farmin	Basin Dakota 11. SEC., T., R., M., OR BLK. AND SURVEY OR			
4. LOCATION OF WELL (REPORT LO		AREA		5
below.)	Sec 14 T24		CTATE	
AT SURFACE: 1520' AT TOP PROD. INTERVAL:	San Juan	DR PARISH 13	NM	
AT TOTAL DEPTH:		14, API NO.		· NPI
16. CHECK APPROPRIATE BOX TO I	NDICATE NATURE OF NOTICE	14. API NO.		
REPORT, OR OTHER DATA		15 FLEVATIO	NS (SHOW DE	, KDB, AND WD)
		6857' GL		i i i i i i i i i i i i i i i i i i i
REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:		· .	
TEST WATER SHUT-OFF				
FRACTURE TREAT		garantin territoria. Propried tracting	等等。———————————————————————————————————	
SHOOT OR ACIDIZE L	XX	(NOTE: Report	results of multip	e combiletion or zone
PULL OR ALTER CASING			on Form 9–330.	1007
MULTIPLE COMPLETE				OIL CON COM.
CHANGE ZONES ABANDON*	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			DIST. 3
(other)		e version and the second		
17. DESCRIBE PROPOSED OR COMPL including estimated date of startin measured and true vertical depths	ng any proposed work. If well is o	lirectionally drille	etails, and give d, give subsurf	e pertinent dates, ace locations and
See rev	erse for details of Ga	llun nerfs a	and frac A	-
Jee Tev	erse for details of da		4-28-82.	
				•
				1 - - - - - - - - - - -
				•
				•
Subsurface Safety Valve: Manu. and Ty	na .		Set @	Ft.
18 herety certify that the foregoing is	strue and correct ugan _{TITLE} Petroleum En	ginoon /	1_20_92	
sic £5. Description A. Di			- 1000	
U	(This space for Federal or State of	fice use)		
APPROVED BY	TITLE	DATE _	·	