submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

,	/,		•	
	/	-, - -		=

BUREAU OF LAND MANAGEMENT	/ XEQUIVEO	
Sundry Notices and Reports on	Wells	
. Type of Well GAS	5. Lease Number NM-45209 6. If Indian, All.or Tribe Name 7. Unit Agreement Name	
 Name of Operator Meridian Oil Inc. Address & Phone No. of Operator Box 4289, Farmington, NM 87499 (505)326-9700 	8. Well Name & Number F-18-24-9 #2 9. API Well No.	
4. Location of Well, Footage, Sec, T, R, M. 990'N, 1650'W Sec. 18, T-24-N, R-9-W, NMPM	Bisti Lower Gallup Ext 11.County and State San Juan County, NM	
Type of Submission Notice of Intent Recompletion Plugging Back	OTICE, REPORT, OTHER DATA of Action Change of Plans New Construction Non-Routine Fracturing Water Shut Off Conversion to Injection	
13. Describe Proposed or Completed Operations Meridian Oil Inc. has found that Union Texas Periodication on 10-6-88 to locate and repair a susy was located in the tbg while TOOH. A pkr was 1500# with no bleed off. TOOH w/pkr, acidized perforations. TIH w/179 jts 2 3/8", 4.7# tbg 5/8" rods set @ 5367'. Released rig 10-11-88.	set @ 5288'. The CSG was r	
	SEP2 5 1991. OIL CON. DIV.	
14. I hereby certify that the foregoing is to Signed Manager Title Regulator		
(This space for Federal or State office use)	DATE	
APPROVED BYTITLE CONDITION OF APPROVAL, IF ANY:	Sun	