

UNITED STATES
DEPARTMENT OF INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back
to a different reservoir. Use Form 3160-3 for such proposals.)

RECEIVED
APR 19 1993

OIL CON. DIV.
DIST. 3

1. Type of Well

OIL WELL

2. Name of Operator

MAX WEEB

3. Address and Telephone Number

(505) 327-7259

c/o DAVE SIMMONS, BOX 48, FARMINGTON, NM 87499

4. Location of Well (Sec. T., R., M., or Survey Description)

990' FWL & 1650' FSL

Sec 6, T24N, R9W

5. Lease Designation and Serial No.

NM 45206

6. If Indian, Allottee or tribe Name

7. If Unit or CA, Agreement Number

8. Well Name and No.

FEDERAL 6 - 1

9. API Well No.

30-045-25298

10. Field and Pool, or Exploratory Area

BISTI GALLUP

11. County or Parish, State

San Juan County, New Mexico

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other _____

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Disposal Water

(Note: Report result of multiple completion on Well
Completion or Recompletion Report and Log form.)

13. Describe Proposed Completion Operations (Clearly state all pertinent details, and give pertinent dates, including estimated starting and proposed work. If well is directionally drilled
give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

OPERATOR SEEKS APPROVAL TO PLUG TO ABANDON THE SUBJECT WELL AS FOLLOWS:
OPERATIONS TO BEGIN AS SOON AS APPROVAL GRANTED.

1. SQUEEZE THE GALLUP PERFORATIONS @ 5246 - 5480 (234' - 31 cu. ft.) WITH
150 SACKS CLASS B NEAT CEMENT (177 cu. ft.)
2. SPOT 150 SACKS (177 cu. ft.) OF CLASS B NEAT CEMENT FROM 4350' TO 3025'.
3. PLACE A 50" CEMENT PLUG AT THE SURFACE INSIDE THE 5-1/2" CASING.
4. CEMENT THE 8-5/8 x 5-1/2" ANNULUS WITH 50 SACKS (59 cu. ft.) CLASS B NEAT CEMENT.
5. REMOVE THE WELL HEAD AND INSTALL A 4-1/2" PERMANENT DRY HOLE MARKER
6. LOCATION WILL BE RECLAIMED AS PER BLM SPECIFICATIONS.

RECEIVED
BLM
93 APR 13 11:12
070 FARMINGTON, NM

NOTE: This format is Issued in lieu of U.S. BLM Form 3160-5

14. I hereby certify that the foregoing is true and correct.

SIGNED

R. D. SIMMONS

TITLE AGENT

DATE: 04/12/93

(This space for Federal or State office use.)

APPROVED BY

**SEE ATTACHED FOR
CONDITIONS OF APPROVAL**

DATE:

CONDITIONS OF APPROVAL, IF ANY

APPROVED
APR 15 1993
DISTRICT MANAGER

NMOCD

THE
OFFICE OF THE
ATTORNEY GENERAL
STATE OF TEXAS
AUSTIN, TEXAS

RECEIVED
JAN 10 1960

STATE OF TEXAS

OFFICE OF THE ATTORNEY GENERAL

IN REPLY REFER TO
(019)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA
1235 LA PLATA HIGHWAY
FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 1-6 Federal

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."

2. Mark Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907

3. Blowout prevention equipment is required.

4. The following modifications to your plugging program are to be made (when applicable):

- 1) Place a cement plug from 5480' to 5126'; tag toe if a retainer is not used. (Top of Gallup 5176')
- 2) Place a cement plug inside the casing from 3321' to 3221' plus 50% excess. (Top of MUE 3271')
- 3) Place a cement plug inside the casing from 1816' to 1516' plus 50% excess. (Top of PC 1766', Top of FRE 1566')
- 4) Place a cement plug from 1085' to 887' inside the casing plus 50% excess. (Top of Hume 937' to 1035')
- 5) Circulate cement from 344' to the surface inside the casing.

Office Hours: 7:45 a.m. to 4:30 p.m.