

Form 3160-5
(June 1990)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. NM 16759
2. Name of Operator Dugan Production Corp.	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. P.O. Box 420, Farmington, NM 87499 (505) 325-1821	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1520' FSL & 790' FWL Sec. 5, T24N, R9W	8. Well Name and No. Big Bird No. 1
	9. API Well No. 30 045 25451
	10. Field and Pool, or Exploratory Area Basin Dakota
	11. County or Parish, State San Juan County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion (Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)^a

2/16/96 Resumed fishing operations. Fished for 6 days and cleaned out to 3495'. Tubing extremely corroded. Suspend fishing operations.

It is intended to plug and abandon as follows:

- 1.) Set a cement retainer @ 3490'. Squeeze cement with 255 ft³ class "B" cement to fill to bottom perforation at 6439'. Cap retainer with 50' cement.
- 2.) Pull up hole to 2665'. Spot 100' class "B" plug to cover top of Mesa Verde. Top of plug @ 2565'.
- 3.) Pull up hole to 1794'. Spot class "B" plug from 1794' to 1482' to cover both PC and Fruitland tops.
- 4.) Pull up hole to 1059'. Spot class "B" plug from 1059' to 800' to cover Ojo Alamo formation.
- 5.) Pull up hole to 269'. Fill casing full with cement to surface. Tie onto bradenhead. If rate is established, squeeze with sufficient amount of cement to fill to base of surface casing.
- 6.) Cut off wellhead and install dry hole marker.

Verbal approval was received from Steve Mason (BLM) on 4/24/96.

14. I hereby certify that the foregoing is true and correct

Signed GARY BRINK
(This space for Federal or State office use)Title Operations ManagerDate 4/26/96Approved by _____
Conditions of approval, if any:

Title _____

Date _____

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

NMOCD