

(SUBMIT IN TRIPLICATE)

Indian Agency _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

_____ **Albuquerque** _____

Allottee **Contract #130**

Lease No. _____

31		
		2

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	2
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

RECEIVED
OCT 15 1957
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 14, 19 **57**

Well No. **"C" 13-31** is located **1830** ft. from **[N]** line and **800** ft. from **[E]** line of sec. **31**

NE/4 SE/4 31 (1/4 Sec. and Sec. No.)
26N 4W (Twp.) (Range)
100W (Meridian)
Wilcox (FC) (Field)
Rio Arriba (County or Subdivision)
New Mexico (State or Territory)

The elevation of the **well head** above sea level is **6734** ft.

DETAILS OF WORK

(State name, of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drill 6-1/4" hole to 1330' and set 1330.05' of 5" (10 3-35 11.35 8-10 casing with Baker float shoe at 1330'. Cemented w/100 on reg. 100 4 pm 10-10-57. HW and released rig 7 am 10-11-57. NO CR.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Northwest Production Corp.**

Address **300 Stamm Building**

Albuquerque, New Mexico

By **Ray Phillips**

Title **Asst Mgr. Prod Opr**