Oil Reports and Gas Services

P. O. BOX 763 HOBBS. NEW MEXICO

August 6, 1964

A. R. Kendrick Oil Conservation Commission 1000 Rio Brazos Road Aztec, New Mexico

> Re: Dr. Sam G. Dunn Grevey #2 D - 35 - 36N - 1E

Dear Mr. Kendrick:

This is in answer to your letter of August 5th requesting formation tops on the subject well.

As you will note from the Federal Form 9-330, no electrical logs were run, and we have no information in our files indicating that sample tops were picked at the time the well was drilled.

By a copy of this letter we are asking Dr. Dunn to please check his records and advise you all possible formation tops available from the driller's log, strip log or other sources.

Yours very truly,

OIL REPORTS AND GAS SERVICES

W. I. Smith

DH/be

cc: Dr. Sam G. Dunn 1312 Main Lubbock, Texas

