## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

BUREAU OF LAND MANAGEMEN	<b>r</b> 
Sundry Notices and Reports on	Wells
1. Type of Well GAS	5. Lease Number SF-080560 6. If Indian, All.or Tribe Name
2. Operator Meridian Oil Inc.	7. Unit Agreement Name
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499	8. Farm or Lease Name Klein A 9. Well No.
4. Location of Well 620'N, 1400'E	10.Field,Pool, Wildcat S.Blanco Pic.Cliffs 11.Sec. T. R. M. or Blk Sec.31,T-26-N,R-6-W NMPM
14. Permit No. 15. Elevations 6196' GR	12.County 13. State San Juan NM
16. Intent to/Subsequent Report of : Recompleti	Lon
17. Describe proposed or completed operations:	
It is intended to recomplete the well in the following MOL&RU. Kill well. NU BOP. TOOH & LD 1 1/4" the 2363'. Set BP @ 2295'. PT csg 3000#/30 min. If cw/test pkr and squeeze, if repairable. If csg h 2395-500' and perforate at approximately 2148-22 treat. Land the and return well to production.	g. Clean out to COTD @ csg fails, isolate leaks nolds, run GR-CCL-Neutron
	17 6 6 2 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
18. Authorized by: San Sradfield Regulatory Affairs	(RS) OH CON. DIV
NOTE: This format is issued in lieu of US BLM Fo	orm 3160-5
	APPROVE
(This space for Federal or State office use)	NOV 14 1989
APPROVED BY TITLE	AREAT MANAGER