

NORTHWEST PRODUCTION CORPORATION

ALBUQUERQUE, NEW MEXICO

October 24, 1958

REPLY TO:
520 SIMMS BUILDING
ALBUQUERQUE, NEW MEXICO

Oil Conservation Commission
State of New Mexico
1000 Rio Brazos Road
Aztec, New Mexico



Gentlemen:

Following are results of packer leakage test completed on our "C" Well 2-29, a Mesaverde-Graneros-Dakota dual, located in the SW/4, Section 29, T-26-N, R-24-W, Rio Arriba County, New Mexico

<u>Date</u>	<u>Deadweight</u> <u>Pressure Taken</u>	<u>Length</u> <u>of Test</u>	<u>Pressure</u>		<u>Remarks</u>
			<u>MV</u>	<u>DK</u>	
9-16-58			1028	1570	7-Day Shut In
9-19-58		3 Days	1036	509	Dakota Flowing - Mesaverde SI
9-23-58		4 Days	1062	465	Dakota Flowing - Mesaverde SI
9-27-58		4 Days	1094	1095	Both Zones Shut In
9-30-58		3 Days	1098	1095	Both Zones Shut In
10-4-58		4 Days	487	632	Mesaverde Flowing - Dakota SI
10-8-58		4 Days	509	625	Mesaverde Flowing - Dakota SI
10-10-58		2 Days	480	1220	Mesaverde Flowing. Dakota blown to atmosphere 40 mins. to clean out liquids and then SI. Dakota pressure obtained 15 hrs. after blow.
10-14-58		4 Days	478	606	Mesaverde Flowing - Dakota SI
10-21-58		7 Days	(See attached bottom hole pressure survey)		

Very truly yours,

NORTHWEST PRODUCTION CORPORATION

RAY PHILLIPS

Ray Phillips, Manager
Production Operations