

"E" 7-28 MESAVERDE
NE SECTION 28-26-3, RIO ARRIBA COUNTY

TOTAL DEPTH: 6277 feet

CASING RECORD: 7-5/8" casing at 4125' with 150 sacks with 8% gel and 50 sacks neat. Top of cement outside casing at 3760' by temperature survey. 5½" liner from 4020'-6277' with 200 sacks. Perforated two holes at 6038', set retainer at 5998' and squeezed 45 sacks to formation.

COMPLETION INTERVAL: Perforations 5640'-6190'. Baker Model EGJ production packer at 5479'.

PRODUCTION HISTORY: IP 1,975 MCFD. First delivery 2-27-58 with cumulative production 34,680 MCF through April, 1960. Rupture disc in dehydrator blew out with well blowing to atmosphere for 50 hours. Unable to build up sufficient pressure to clean well.

STATUS: Casing, tubing and wellhead equipment in place. Pipeline has not been disconnected.

INTENT: To regain production it would be necessary to thoroughly clean the well by swabbing. Production would not be sufficient to justify the expense at this time; however permanent abandonment of the Mesaverde is not desirable.