## UNITED STATES SUBMIT IN TRIPLICATE® DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

•	,	_	v	_		•	,		<b>١</b>	•	٠,	٠,	٠,	 •								
 _		_	_		_	_	_	_		_	_			_	 _	_	_	 	 _	•	 	-
													_			_						

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

7.	UNIT	AGREEMENT	NAME

North Lindreth Unit

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

10. FIELD AND POOL, OR WILDCAT Blanco Mesa Verde Gavilan Pictured Cliff

8. FARM OR LEASE NAME

9. WELL NO.

2.	NAME	OF	OPERATOR	

J. Gregory Merrion and Robert L. Bayless

OTHER

3. ADDRESS OF OPERATOR

P.O. Box 507, Farmington, New Mexico 87401

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)

At surface

14. PERMIT NO.

(Other)

OIL U

990' FWL and 990' FSL

GAS Well X

> Sec. 20, T26N, R2W 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH | 13. STATE

> > 7380 ground

Rio Arriba New Mexico

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REPAIRING WELL PULL OR ALTER CASING TEST WATER SHUT-OFF WATER SHUT-OFF MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING FRACTURE TREAT SHOOTING OR ACIDIZING ABANDONMENT\* SHOOT OR ACIDIZE ABANDON\* CommingTing Zones REPAIR WELL CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

- 8-14-76 Moved in Big "A" Well Service rig.
- Killed well, pulled 2-3/8" tubing from picture cliff side. Pulled 2-3/8" tubing 8-16-76 from mesa verde side.
- 8-17-76 Run in the hole with 2-3/8" tubing and mill. Tagged Baker Model "DA" packer and milling.
- Completed milling on packer. Pulled tubing out of the hole.
- Ran in with 2-3/8" tubing single production string. Landed tubing. Made up 8-19-76 wellhead and closed well in.
- 8-20-76 Released rig.

18, I	hereby	certify	that	bje i	foregoing	<b>z</b> 18	true	and	forrec

Engineer TITLE

1976

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: TITLE

DATE