

Remade card

F. Loc. 1500/S; 790/E Elev. 6372 GL Spd. 6/2/53 Comp. 6/29/53 TD 2800 PB
 Casing S. 9-5/8 @ 92 W. 85 Sx. Int. @ W Sx. Pr. 7 @ 2710 W 115 Sx. T. 1 @ 2793
 Csg. Perf. Prod. Stim. Shot 320 qts 2718-2800

I.P. 4839 MCF/D After 3 Hrs. SICP 1095 PSI After 7 Days GOR Grav. 1st Del. 12/17/53 EPNG

TOPS		NITD	X	Well Log	X	TEST DATA						Ref. No.
Kirtland		C-102		Plat	X	Schd.	PC	Q	PW	PD	D	
Fruitland		C-103	X X	Electric Log								
Pictured Cliffs	2710	C-104	X X	C-110	X		835	990	246	250	987	
Cliff House						54					837	
Menefee		Ditr Workover		Dfa	6/28/55	795	864	236	598	731		
Point Lookout		Datr 11/17/55		Dac 12/1/55	11/7/55	1292	354	332	1252	#11.0		
Mancos		* <u>WP</u> Remarks 7/21-7/24/55 - SOf 2710-2800 w/3040 G, 3040 # Cp. from Pubco Dev. Inc.			11/7/55	643	1530	302	332	994		
Tocito					5/13/55	159	1116	332	332	1112		
Dakota												
Morrison												
Entrada					10-14/55	550	707	237	254	652		
					11/7/55	159	1116	332	332	994		
					8/1/56	457	559	236	229	568		
					2/6/55	475	622	552	848	250		
PCD	3672											

P
 o So B1 PC Co. RA S 23 T 26N R 6W U I Jan. | Feb. | Mar. | Apr. | May | June | July | Aug. | Sept. | Oct. | Nov. | Dec.
 I Over Pubco Pet. Lse Buttram No. 23-4