

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other
2. NAME OF OPERATOR
El Paso Natural Gas Company
3. ADDRESS OF OPERATOR
P. O. Box 990, Farmington, N.M. 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1095' S, 1065' E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Well Status

SUBSEQUENT REPORT OF:

- ☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE
Contract No. 108
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Tribal
7. UNIT AGREEMENT NAME
Jicarilla Tribal
8. FARM OR LEASE NAME
Jicarilla G
9. WELL NO.
12
10. FIELD OR WILDCAT NAME
So. Blanco P.C.
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 13, T26N, R5W
12. COUNTY OR PARISH
Rio Arriba
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
7199' DF

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is requested this well be classified as temporarily abandoned pending outcome of an evaluation for workover or P & A.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Div. Production Eng. DATE 12-20-78

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

FEDERAL SURFACE

Attachment to Notice of
Intention to Abandon

U. S. GEOLOGICAL SURVEY
P. O. Box 959
Farmington, New Mexico 87401

3-18-81

Re: Permanent Abandonment

Well: #12 Jicarilla G

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".
2. The Farmington office (telephone (505) 325-4572) is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. We have asked the Bureau of Land Management for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
5. The surface management agency is to be notified when surface rehabilitation is complete.
6. The following modifications to your plugging program are to be made (when applicable):
 - a) Perforate 5 1/2" casing at 3510' and place cement plug inside and outside casing to 2968'
 - ~~b) Perforate 5 1/2" casing at 212' and place cement plug inside and outside casing to surface.~~
 - b) Place cement plug inside casing from 1550' to 1450'.

Office Hours: 8:00 A.M. to 5:00 P.M.
Farmington Personnel to be notified:

Home Telephones:

Ray Swanson: Petroleum Engineering Technician - 325-8189
Fred Edwards: Petroleum Engineering Technician - 325-7885
Ken Baker: Petroleum Engineering Technician - 327-2170