

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
Jic.Contract 109

SUNDRY NOTICES AND REPORTS ON RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

DEC 04 1986

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Meridian Oil Inc.

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

3. ADDRESS OF OPERATOR
Post Office Box 4289, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below) 1800'S, 1750'E
At surface

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jicarilla F

9. WELL NO.
11

10. FIELD AND POOL, OR WILDCAT
S. Blanco Pic. Cliffs

11. SEC., T., R., M., OR BLK. AND
SUBST. OR AREA
Sec. 16, T-26-N, R- 5-W
N.M.P.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
'GL

12. COUNTY OR PARISH
Rio Arriba

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

It is intended to plug and abandon this well by:
Move on location and rig up.

Release Otis "MR" packer at 3073' and TOOH.

plug 2872'-2972' TIH w/ 1 1/4" tbg and spot 10 sx. plug from 3222-3060'.

Circulate hole with 30 bbls. of 9# mud.

TOH and shoot two holes at 2875'. TIH. Spot 25 sx plug
across Ojo Alamo.

TOH and shoot two holes at 1200'. TIH. Spot 20 sx. plug.

TOH and shoot two holes at 150'. Circulate 40 sx. cement to surface.

Set dry hole marker.

In view of current economic conditions, we request a delay before plug and
abandoning this location.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Drilling Clerk

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

DEC 04 1986

AREA MANAGER

*See Instructions on Reverse Side

NMOCC