Form	9-331
(May	1963)

WELL

NAME OF OPERATOR

3. ADDRESS OF OPERATOR

UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

SUBMIT IN TRIPLICATE*

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

Jicarilla Cont. 110 6. IF INDIAN, ALLOTTEE OR TRIBE NAME

GEOLOGICAL SURVEY							
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS		

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

Jicarilla

7.	CNIT AGR	EEMENT	NAME	
8.	FARM OR	LEASE	NAME	

Jicarilla A 9. WELL NO.

1

10. FIELD AND POOL, OR WHILE CO.

Basin Dakota & Blanco MV 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 18, T26N, R5W

12. COUNTY OR PARISH 13. STATE New Mexico Rio Arriba

14. PERMIT NO.

FRACTURE TREAT

REPAIR WELL

(Other)

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6599' GR

16.

GAS . WELL

Tenneco Oil Company

X

OTHER

1200 Lincoln Tower Bldg., Denver, Colorado

1820' FSL and 1130' FWL

LOCATION OF WELL (Report location clearly and in accordance with any State respectively space 17 below.)

At surface

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

PULL OR ALTER CASING TEST WATER SHUT-OFF MULTIPLE COMPLETE ABANDON* SHOOT OR ACIDIZE

CHANGE PLANS

WATER SHUT-OFF PRACTURE TREATMENT SHOOTING OR ACIDIZING

uirements.

REPAIRING WELL ALTERING CASING ABANDONMENT'

(Other) _ (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated-date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zoner pertinent to this work.)*

Packer leakage has been repaired, as follows:

- MIRU pulling unit and unseated seal assembly from Mod "N" pkr.
- Circulated hole with hot oil to remove paraffin and scale.
- Pulled the and redressed seal assembly, replaced blast jts and sliding sleeve.
- RIH, hydrotested tbg, stung into Mod "N" pkr.
- Swabbed in Dakota.
- Placed on line.
- Ran packer leakage test 8/10/74.

RECEIVE

AUG 21 1974

U. S. GEOLOGICAL SURVEY FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct					1			
SIGNED Taul Togers	TITLE _	Sr.	Production	Clerk		DATE _	8/19/74	
(This space for Federal or State officeruse)								
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE _					DATE _		