NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

			raya T	2250 Tanna		11 a man 1 a a
perator	CONSOLIDAT	ED OIL & GAS]	TMC	$-\frac{16000}{1}$	<i>T</i>	No. A (MD)
ocation	R			·		
f Well: Un	it_P_Sec	13 Twp	26 Rg	e4	County	Rio Arriba
			Type of Prod	. Method	of Prod.	Prod. Medium
	Name of Rese	rvoir or Pool	(Oil or Gas)	(Flow or	Art. Lift)	(Tbg. or Csg.)
per		_			•	
mpletion	MESA VERD	E	GAS	FL	OW	TBG
wer	- 4 4		1	77	~:	mn a
mpletion	DAKOTA	ו שמת	GAS FLOW SHUT-IN PR	FLO	.W	TBG
111			of	SI pre		Stabilized?
per Hour,	date -in 5-28-79	Length	nt — in 2 — Dozza			(Xes or No) No
wer Hour,		Length	ut-in 3-Days of	ST pre	55.	Stabilized?
	<u>-in 5-28-79</u>	time sh	ut-in 3-Days	psig	514	(Xes or No) No
mp1 onde	<u> </u>	, Julia Dir.	FLOW TEST N	0. 1		
mmenced at	(hour, date)	* 5-31-7°)	Zone p	roducing (Uppe	r or Lower): Low
Time	Lapsed time	Pre) ssure	Prod. Zone		
our. date)	since*	Upper Compl.	Lower Compl.	Temp.	Rem	arks
5-29-79	1-Day	401	498		Both Zones	Shut In
5-30-79	2-Days	409	510		Both Zones	Shut In
,				1	7.43	a)
5 -31- 79	3-Days	415	514		Both Zones	Snut In
	1, -	1.35	201		Town Zame	El aui na
6-1-79	1-Day	417	304	 	Lower Zone	LTOMING
6 - 2 - 79	2-Days	418	301		Lower Zone	Flowing
0-2-19	Z-Days	410	301		DOWEL DOILE	T-15W11IR
		1177				
		Length	rest shur-in pr of	SI pre	SS•	Stabilized?
oper Hour,	-in	Length time sh	rest shur-in PR of ut-in	SI pre	SS•	Stabilized? (Yes or No)
ompl Shut	-in date	Length time sh Length	rest Shur-IN PR of ut-in of	SI pre ssig	ss. ss.	Stabilized?
ompl Shut	-in	Length time sh Length	TEST SHUT-IN PR of ut-in of ut-in	SI pre psig SI pre psig O. 2	ss. ss.	Stabilized? (Yes or No) Stabilized? (Yes or No)
ompl Shut ower Hour, ompl Shut	-in date -in	Length time sh time sh	TEST SHUT-IN PR of ut-in of ut-in FLOW TEST N	SI pre sig SI pre psig SI pre psig Co. 2 Zone p	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No)
mpl Shut wer Hour, mpl Shut mmenced at	-in date -in (hour, date) Lapsed time	Length time sh Length time sh	TEST SHUT-IN PR of ut-in of ut-in FLOW TEST N	SI pre sig SI pre psig SI pre psig O. 2 Zone p [Prod. Zone	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower):
mpl Shut wer Hour, mpl Shut mmenced at	-in date -in (hour, date) Lapsed time	Length time sh Length time sh	TEST SHUT-IN PR of ut-in of ut-in	SI pre sig SI pre psig SI pre psig O. 2 Zone p [Prod. Zone	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No)
ompl Shut ower Hour, ompl Shut ommenced at	-in date -in (hour, date) Lapsed time	Length time sh Length time sh	TEST SHUT-IN PR of ut-in of ut-in FLOW TEST N	SI pre sig SI pre psig SI pre psig O. 2 Zone p [Prod. Zone	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower):
mpl Shut wer Hour, mpl Shut mmenced at	-in date -in (hour, date) Lapsed time	Length time sh Length time sh	TEST SHUT-IN PR of ut-in of ut-in FLOW TEST N	SI pre sig SI pre psig SI pre psig O. 2 Zone p [Prod. Zone	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower):
mpl Shut wer Hour, mpl Shut mmenced at	-in date -in (hour, date) Lapsed time	Length time sh Length time sh	TEST SHUT-IN PR of ut-in of ut-in FLOW TEST N	SI pre sig SI pre psig SI pre psig O. 2 Zone p [Prod. Zone	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower):
mpl Shut wer Hour, mpl Shut mmenced at	-in date -in (hour, date) Lapsed time	Length time sh Length time sh	TEST SHUT-IN PR of ut-in of ut-in FLOW TEST N	SI pre sig SI pre psig SI pre psig O. 2 Zone p [Prod. Zone	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No)
mpl Shut wer Hour, mpl Shut mmenced at	-in date -in (hour, date) Lapsed time	Length time sh Length time sh	TEST SHUT-IN PR of ut-in of ut-in FLOW TEST N	SI pre sig SI pre psig SI pre psig O. 2 Zone p [Prod. Zone	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower):
mpl Shut wer Hour, mpl Shut mmenced at	-in date -in (hour, date) Lapsed time	Length time sh Length time sh	TEST SHUT-IN PR of ut-in of ut-in FLOW TEST N	SI pre sig SI pre psig SI pre psig O. 2 Zone p [Prod. Zone	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower):
mpl Shut wer Hour, mpl Shut mmenced at	-in date -in (hour, date) Lapsed time	Length time sh Length time sh	TEST SHUT-IN PR of ut-in of ut-in FLOW TEST N	SI pre sig SI pre psig SI pre psig O. 2 Zone p [Prod. Zone	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower):
mpl Shut wer Hour, mpl Shut mmenced at	-in date -in (hour, date) Lapsed time	Length time sh Length time sh	TEST SHUT-IN PR of ut-in of ut-in FLOW TEST N	SI pre sig SI pre psig SI pre psig O. 2 Zone p [Prod. Zone	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower):
mpl Shut wer Hour, mpl Shut mmenced at	-in date -in (hour, date) Lapsed time	Length time sh Length time sh	TEST SHUT-IN PR of ut-in of ut-in FLOW TEST N	SI pre sig SI pre psig SI pre psig O. 2 Zone p [Prod. Zone	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No)
mpl Shut wer Hour, mpl Shut mmenced at	-in date -in (hour, date) Lapsed time	Length time sh Length time sh	TEST SHUT-IN PR of ut-in of ut-in FLOW TEST N	SI pre sig SI pre psig SI pre psig O. 2 Zone p [Prod. Zone	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No)
mpl Shut wer Hour, mpl Shut mmenced at	-in date -in (hour, date) Lapsed time	Length time sh Length time sh	TEST SHUT-IN PR of ut-in of ut-in FLOW TEST N	SI pre sig SI pre psig SI pre psig O. 2 Zone p [Prod. Zone	ss. ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower):
mpl Shut wer Hour, mpl Shut mmenced at Time mour, date)	-in date -in (hour, date) Lapsed time since **	Length time sh Length time sh lime sh length time s	of ut-in of ut-in FLOW TEST N ssure Lower Compl.	SI pre psig SI pre psig O. 2 Zone p Prod. Zone Temp.	ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) er or Lower): marks
mpl Shut wer Hour, mpl Shut mmenced at Time mour, date)	-in date -in (hour, date) Lapsed time since **	Length time sh Length time sh lime sh length time s	of ut-in of ut-in FLOW TEST N ssure Lower Compl.	SI pre psig SI pre psig O. 2 Zone p Prod. Zone Temp.	ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) er or Lower): marks
mpl Shut wer Hour, mpl Shut mmenced at Time our, date)	-in date -in (hour, date) Lapsed time since **	Length time sh Length time sh lime sh length time s	of ut-in of ut-in FLOW TEST N ssure Lower Compl.	SI pre psig SI pre psig O. 2 Zone p Prod. Zone Temp.	ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) er or Lower): marks
mpl Shut wer Hour, mpl Shut mmenced at Time our, date) coduction r l:	-in date -in (hour, date) Lapsed time since ** ate during te	Length time sh Length time sh Pre Upper Compl. est cased on MCFPD; Teste	of ut-in of ut-in FLOW TEST N ssure Lower Compl.	SI pre psig SI pre psig O. 2 Zone p Prod. Zone Temp.	ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) er or Lower): marks
mpl Shut wer Hour, mpl Shut mmenced at Time our, date) coduction r l:	-in date -in (hour, date) Lapsed time since **	Length time sh Length time sh Pre Upper Compl. est cased on MCFPD; Teste	of ut-in of ut-in FLOW TEST N ssure Lower Compl.	SI pre psig SI pre psig O. 2 Zone p Prod. Zone Temp.	ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) er or Lower): marks
mpl Shut wer Hour, mpl Shut mmenced at Time our, date) coduction r l:	-in date -in (hour, date) Lapsed time since ** ate during te	Length time sh Length time sh Pre Upper Compl. est cased on MCFPD; Teste	of ut-in of ut-in FLOW TEST N ssure Lower Compl.	SI pre psig SI pre psig O. 2 Zone p Prod. Zone Temp.	ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) er or Lower): marks
mpl Shut wer Hour, mpl Shut mmenced at Time nour, date) roduction r il: as:	-in date -in (hour, date) Lapsed time since ** ate during te	Length time sh Length time sh W** Pre Upper Compl. est pased on MCFPD; Teste	Bbls. in_d thru (Orifice	SI pre psig SI pre psig O. 2 Zone p [Prod. Zone Temp. Hrs. or Meter):	ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) er or Lower): marks GOR
mpl Shut wer Hour, mpl Shut mmenced at Time nour, date) roduction r il: as: MARKS:	-in date -in (hour, date) Lapsed time since ** ate during te	Length time sh Length time sh W** Pre Upper Compl. est pased on MCFPD; Teste	Bbls. in_d thru (Orifice	SI pre psig SI pre psig O. 2 Zone p [Prod. Zone Temp. Hrs. or Meter):	ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) er or Lower): marks GOR
ompl Shut ower Hour, ompl Shut ommenced at Time nour, date) roduction r il: as: hereby cer	-in date -in (hour, date) Lapsed time since ** ate during te	Length time sh Length time sh W** Pre Upper Compl. est pased on MCFPD; Teste	TEST SHUT-IN PROOF of out-in of out-in FLOW TEST Nossure Lower Compl. Bbls. in d thru (Orifice thru)	SI pre psig SI pre psig O. 2 Zone p Prod. Zone Temp. Hrs. or Meter):	roducing (Uppe Rem Grav.	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower): marks GOR
mmpl Shut ower Hour, ompl Shut ommenced at Time our, date) roduction r il: as: MARKS: hereby can nowledge.	-in date -in (hour, date) Lapsed time since ** ate during te BOPD to	Length time sh Length time sh Pre Upper Compl. est based on MCFPD; Teste	TEST SHUT-IN PROOF of out-in of out-in FLOW TEST Not saure Lower Complement of thru (Orifice therein contains operations)	SI pre psig SI pre psig O. 2 Zone p Prod. Zone Temp. Hrs. or Meter):	ss. roducing (Uppe	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower): marks GOR
ompl Shut ower Hour, ompl Snut ommenced at Time nour, date) roduction ril: as: hereby cer nowledge.	-in date -in (hour, date) Lapsed time since ** ate during te BOPD	Length time sh Length time sh X* Pre Upper Compl. Active St Dased on MCFPD; Teste	Bbls. in d thru (Orifice	SI pre psig SI pre psig SI pre psig O. 2 Zone p Prod. Zone Temp. Hrs. or Meter):	roducing (Uppe Rem Grave	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower): arks GOR the best of my GAS INC
ompl Shut ower Hour, ompl Snut ommenced at Time nour, date) roduction ril: as: hereby cer nowledge. oproved: New Mexico	-in date -in (hour, date) Lapsed time since ** ate during to BOPD to	Length time sh Length time sh X** Pre Upper Compl. MCFPD; Teste information // 19 tion Commission	Bbls. in Bbls. in d thru (Orifice herein contains Operat	SI pre psig SI pre psig SI pre psig O. 2 Zone p Prod. Zone Temp. Hrs. or Meter): d is true s or CONS	roducing (Uppe Rem Grav. Grav. OLIDATED OIL &	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower): arks GOR the best of my GAS INC
ompl Shut ower Hour, ompl Snut ommenced at Time nour, date) roduction ril: as: hereby can owledge. oproved: New Mexico	-in date -in (hour, date) Lapsed time since ** ate during to BOPD to	Length time sh Length time sh X** Pre Upper Compl. MCFPD; Teste information // 19 tion Commission	Bbls. in Bbls. in d thru (Orifice herein contains Operat	SI pre psig SI pre psig SI pre psig O. 2 Zone p Prod. Zone Temp. Hrs. or Meter): d is true s or CONS	roducing (Uppe Rem Grav. Grav. OLIDATED OIL &	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower): arks GOR the best of my GAS INC
mpl Shut wer Hour, mpl Shut mmenced at Time our, date) coduction r l: as: hereby cer nowledge. pproved: lew Mexico Origina	-in date -in (hour, date) Lapsed time since ** ate during te BOPD	Length time sh Length time sh W** Pre Upper Compl. MCFPD; Teste information / J 19 tion Commission AHAVEZ	Bbls. in d thru (Orifice herein contains Operat	SI pre psig SI pre psig SI pre psig SI pre psig O. 2 Zone p Prod. Zone Temp. Hrs. or Meter): d is true s or CONS	roducing (Uppe Rem Grave	Stabilized? (Yes or No) Stabilized? (Yes or No) r or Lower): arks GOR COR GAS INC

NORTHWEST NEW MEXICO PACKER LEAKAGE TEST INSTRUCTIONS

- 1. A packef leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tubing have been disturbed. Tests shall also be taken at any time that communication is suspected or when requested by the Commission.
- At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Commission in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3. The packer lemmage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: If, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.
- 5. Following completion of Flow Test No. 1, the well shall again be shutin, in accordance with Paragraph 3 above.
- 6. Flow Test No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedure for Flow Test No. 2 is to be the same as for Flow Test No. 1 except that the previously produced zone shall remain shut-in while the zone which was previously shut-in is produced.

- 7. Pressures for gas-zone tests must be measured on each zone with a deadwoight pressure gauge at time intervals as follows: 3-hour tests: immediately prior to the beginning of each flow-period, at fifteen-minute intervals during the first hour thereof, and at hourly intervals thereafter, including one pressure measurement immediately prior to the conclusion of each flow period. 7-day tests: immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test data.
- 24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges, the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.
- 8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico Oil Conservation Commission of Northwest New Mexico Packer Leakage Test Form Revised 11-1-58, with all deadweight pressures indicated thereon as well as the flowing temperature (yas zones only) and gravity and GOR (oil zones only). A pressure versus time curve for each zone of each test shall be constructed on the reverse side of the Packer Leakage Test Form with all deadweight pressure points taken indicated thereon. For oil zones, the pressure curve should also indicate all key pressure changes which may be reflected by the recording gauge charts. These key pressure changes should also be tabulated on the iront of the Packer Leakage Test Form.

