NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

AR 1 7 1952 OIL CON. COM.

Submit this report in triplicate to the Oil Conservation Commission District Office within ten days after the work specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

| | | | - | | | |
|---|-----------------------------------|---|---|-------------|------------|--------------|
| REPORT ON BEGINNING DRILLING OPERATIONS | | | | | | |
| REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL | | REPORT ON PULLING OR OTH ALTERING CASING | | | R OTHERWI | SE |
| REPORT ON RESULT OF TES SHUT-OFF | ST OF CASING | x | REPORT ON I | EEPENIN | G WELL | |
| EPORT ON RESULT OF PLU | JGGING OF WELL | | | | | |
| | | Mareh | 1 <u>1,</u> 1952 | Allboo | cmercoe l | iow York oo |
| | | | Date | | P. Carre | ace |
| collowing is a report on the world | | | | | | |
| Lowry et al Operating | | | | | | |
| W SV/4 | of Sec 16 | , T | 251 | , R | 6 i | , N. M. P. M |
| Wildest | Pool | Rio . | krriba | | | Count |
| ne dates of this work were as f | ollows: March 3 | 1059 | | | · | |
| At 10 30401. R | am and comented 5 | da 00 e | maing at 29 | 71' with | 200 saeks | la |
| | an and comented 5 y and move out. | | | | | l• |
| | | | | | | • |
| | | | | | |)• |
| | | | | | |) • |
| Tear down retar; | y and move out. | How wai. | ting on Cab | le Tools | • | at. Sunt. |
| Tear down retar; | y and move out. | How wai. | | le Tools | • | et. Supt. |
| | and move out. | Now usi. | ting on Cab | le Tools | • | et. Supt. |
| itnessed by | Name Name Name | is | al Company nereby swear or true and correct. | affirm that | • | Title |