

COPY FOR
STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
SUBMIT IN TRIPPLICATE TO
DISTRICT OFFICE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 072035-A
Unit 36/4 Sec. 9
Designated Drilling Unit

SUNDRY NOTICES AND REPORTS ON WELLS

JAN 18 1952
OIL CON. COM.
DIST. X

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 16, 1952

Well No. PC 177 is located 1550 ft. from S line and 920 ft. from W line of sec. 9

N 36/4 Sec. 9
(1/4 Sec. and Sec. No.)

26E 6W
(Twp.) (Range)

N.M.P.M.
(Meridian)

Wilcox
(Field)

Eliz Arriba
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6511 ft. 21.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

Tested 5 1/2" OD Casing for 3 hours. Tested o.k. *

1-9-52: Dumped 653 quarts SEG 2889' to 2963'. Shot exploded o.k.
Gas measured 1645 MCF 10 hours after drilling plug.
*Method used in testing casing with Cable Tools was to drill out cement plug, let hole stand for 3 hours and then run bailer test for water results. Recovered no water.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company LDAY et al Operating Account

Address Room 219

616 East Central Avenue

Albuquerque, New Mexico

By E. R. Richardson
Title Business Manager