Form 3160-5 (November 1994)

Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

5. Lease Serial No. NMSF-079162

SUNDRY NOTICES AND REPORTS ON WELLS

Change Plans

Do not use this form for proposals to drill or to re-enter an PM 1: 23

6. If Indian, Allottee or Tribe Name

Do not use th abandoned we	ils form for proposals ell. Use Form 3160-3 (APD) for such proposal	2 PA 1. 23								
SUBMIT IN TRIPLICATE - Other Instructions on Province side ON, NM				7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. MKL #8 9. API Well No. 30-039-06572 10. Field and Pool, or Exploratory Area Blanco. S. 11. County or Parish, State							
1. Type of Well Oil Well S Gas Well Other 2. Name of Operator Louis Dreyfus Natural Gas Corpyll (CO) No Divo 3a. Address 14000 Quail Springs Parkway Suite 600, Oklahoma City, OK 73134 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)											
						1650' FSL & 990' FEL NE SE Sec. 7-26N-7W					Arriba, NM
						12. CHECK AF	PROPRIATE BOX(ES	S) TO INDICATE NATU		EPORT, C	OR OTHER DATA
						TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Star	r/Resume)	☐ Water Shut-Off ☐ Well Integrity ☐ Other						
Subsequent Report	Casing Repair	New Construction	Recomplete	1	Ouler						

Plug Back Convert to Injection 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days are application of the involved and true vertical depths of all pertinent markers and zones. following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

Plug and Abandon

Temporarily Abandon

☐ Water Disposal

Work commenced 8/4/98. Spot 75 sks. Cl. H cmt. w/2% CaCl2 + 1/4% sk. cello flake cement plug. Tag cmt. @ 1895'; drill out to 2115' (bottom of 5 1/2" csg.) Drilled out open hole and deepened to 2220' w/4 3/4" bit. Set 4" 10.46# FJ csg. @ 2219'. Cemented csg. w/100 sks. Cl. H + 10% A 10B + 8# sk. gelsonite + 1% CaCl2, followed by 200 sks. Cl. H cmt. + 2% CaCl2. Cleaned out to PBTD of 2205'. Ran CBL & CSL. TOC @ 970'.

Perforated 2123'-2125', 2141'-2149', 2159'-2161', 2164'-2166'w/4 SPF, 56 holes. Acidized w/1000 gal. 15% HCL & 84 ball sealers. Frac w/70Q N2 foam. Used 372,000 SCF N2; 92,000# Arizona 20/40 sand & 10,400# resin coated sand. Circulated sand out of casing.

Set 2 3/8" tbg. @ 2145'. Put well on 2" x 1 1/4" x 7' x 10' RHAC Z pump. Set tank, pumping unit, separator and compressor. Well turned to sales line 8/23/98.

e egulatory Technician te /19/99
OR STATE OFFICE USE
Title Date ACCEPTED FOR RECORD
or office see Office to make to any department or agency of the United States any false, fictitious
e / / Or se