Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0135

	Expires	July 31.	1996	
se	Serial No.			

	BUREAU OF LAND MAN	AGE	MENT	***		5. Lease			
SUMPRY NOTICES AND REPORTS ON WELLS							791		
Do not use the abandoned we	Phase	6. If Indian, Allottee or Tribe Name							
	PLICATE - Other inst		ons on revers	2 7 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	EJYE	7. If Unit	or CA	Agreement, Name and/or No.	
				SEP	0 0	1 <u>1/1</u>			
I. Type of Well Oil Well	Other				2 8 1998	8. Well Name and No. MKL #14			
			(O)[[[030	ाला - जिल		·		
Louis Dreyfus Natur	al Gas Corp.			1000		Vo 30-0			
Address 14000 Quail	Springs Parkway	31	. Phone No. (included) (405) 749-5	de pred	M. 3				
Suite 600. Oklahoma City, OK 73134 (405) 745.						s. I	31an	co P.C.	
4. Location of Well (Footage, Sec.		on)				11. Count	y or Pa	urish, State	
1650' FNL & 990' F						Pio	1	iba, New Mexico	
SW NW Sec. 5-T26N-	R <u>7W</u>					1			
12. CHECK AP	PROPRIATE BOX(ES)	TO 11	IDICATE NATI	JRE O	F NOTICE, R	EPORT, C	OR O	THER DATA	
			Т	YPE O	YPE OF ACTION				
TYPE OF SUBMISSION			Deepen		Production (Star	t/Resume)		Water Shut-Off	
Notice of Intent	Acidize		Fracture Treat	ă	Reclamation	, • 1		Well Integrity	
	Alter Casing		New Construction	ă				Other	
Subsequent Report	Casing Repair	ā		\bar{a}	Temporarily Al	andon			
Final Abandonment Notice	Change Plans	ă	-	ā	Water Disposal				
	Convert to Injection							and approximate duration thereof. of all pertinent markers and zones. orts shall be filed within 30 days. Form 31604 shall be filed once	
2. TOH w/2 3/8" t Clean out to T 3. Spot 75 sx. Cl from TD. WOC 4. PU & RIH w/4" Land casing as and cement 4" (14.6 ppg - 1. WOC ± 8 hrs. R 5. ND BOP's, cut 6. Load and test RD WL.	ubing and packer. D and deepen to 2 . H w/27 CaCl2 an over night and dr 10.46# flush join	2390 ad 1 rill at c as 100 lowe urve asta Run	' if possib /4# cello f out cement asing strin possible. sx. Cl. H + d by 100 sx y if cement 11 head. logs, perf	le. lake . g (± Estal 10% . Cl did	(16.4 ppg 2390') ar blish circ Thixad + . H + 27 (not circu	g-1.08 (culation 17 CaCl2 (culate.) d Cliff:	euft) ft n w/ 12 + 15.7	/sx) cement plug . shoe joint. 2% KC1 water . 8 #/sx. Gilsonite ppg-1.18 cuft/sx) ased on new logs. hallsealers.	
14. I hereby certify that the foregoin Name (Printed/Typed)	ng is true and correct	.000	Title		•			9-23-98	
Terrve D. Bryant					latory Tec	milciai			
Signature / Buy & Bryang					ember 23	1998 NTERE	D		
11	THIS SPACE	E FOI	R FEDERAL OR	STAT	E OFFICE US	EFMSS	_		
Approved by						P 24	Date 1999		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.					— BY ⊅			' Canana any Falsa firtitions of	
Title 18 U.S.C. Section 1001, mal fraudulent statements or representa	for env person ki	nowing jurisd	gly and willfully to oction.	make to	any department	or egency of	the II	nited States any false, fictitious or	

(Instructions on reverse)
Venda / Approval 9/23/98 - 1:05 pm w/sunface strips.

Form 3160-5

Louis Dreyfus Natural Gas Corp.
MKL Well No. 14
Notice of Intent to Acidize, Fracture Treat continued
September 23, 1998

and wait for balls to fall below perfs. Frac PC via 4" casing @ 60 BPM and \pm 2,600 psi surface treating pressure. Pump \pm 50,000 gallons 70 Quality N2 foam (20# XL base) and \pm 90,000# 20/40 Arizona Sand and 10,000# 20/40 RCS.

8. RIH w/2 3/8" tubing & CO to TD w/N2. POOH w/tubing.

9. PU TA & RIH w/2 3/8" production tubing. PU & RIH w/3/4" rod string and 1 1/4" BHP. RDMO WOU. Build pad and install pumping unit. Hang well on.

10. Install wellhead compressor. Turn well to sales.

Anticipate work beginning 9/24/98.