Form 3160-5 (November 1994)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED	
BLM	

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

Loase Serial N	lo.
	_

	BUREAU OF LAND MANA	GEMENI	1	PM 0: 1.5	5. Letase Se	
SUNDR'	Y NOTICES AND REPO	RTS ON 90	eces 24	KIT 9. 43	SF-07	9162
	is form for proposals to II. Use Form 3160-3 (APD					, Allottee or Tribe Name
SUBMIT IN TRI	IPLICATE - Other instru	ıctions on ı	everse side	,	7. If Unit of	or CA/Agreement, Name and/or No.
1. Type of Well  Oil Well X Gas Well	Other		اعالا	15 ii W ie		me and No.
2. Name of Operator Louis Dreyfus Natur				RIA G	MKL #	
Louis Dreylus Natur	Caringe Parkway	3h Phone N	o. (include area	code 1998	<b>1</b> 30-03	39-06712
3a. Address 14000 Quail Suite 600, Oklahoma	City. OK 73134		749-5287			d Pool, or Exploratory Area
4. Location of Well (Footage, Sec.	T. R. M., or Survey Description		श्राप (द्र(	MG JAIC	S. B1	lanco P.C.
				M. 3	1011. County	or Parish, State
1650' FNL & 990' F				ono (a)		Arriba, New Mexico
SW NW Sec. 5-T26N-					_1	
12. CHECK AP	PROPRIATE BOX(ES) TO	O INDICATE			REPORT, OF	KOTHER DATA
TYPE OF SUBMISSION			TYPE	OF ACTION		
	X Acidize	Deepen		Production (Sta	rt/Resume)	☐ Water Shut-Off
Notice of Intent	Alter Casing	Fracture 1	reat 🗆	Reclamation		Well Integrity
Subsequent Report	Casing Repair	New Cons	struction $\Box$	Recomplete		Other
_ 5455455	Change Plans	Plug and	Abandon 🔲	Temporarily A	bandon	
Final Abandonment Notice	Convert to Injection	Plug Baci		Water Disposal	l	
1. MIRU WOU, reve 2. TOH w/2 3/8" t Clean out to T 3. Spot 75 sx. Cl from TD. WOC 4. PU & RIH w/4" Land casing as and cement 4" (14.6 ppg - 1. WOC ± 8 hrs. F 5. ND BOP's, cut 6. Load and test RD WL.	erse circulating equations and packer.  The and deepen to 23 and over night and driver of the casing string w/10 and temperature sure off casing and instanting and instanting. RU WL.	PU 2 3/3 390' if point of the second of the	Load hose tubing ossible. Ilo flake ement. string (± le. Esta. H + 10% 00 sx. Clement did. perforat	le w/2% Ko string, (16.4 pp (2390') a blish cir Thixad + H + 2% I not circ	C1 water. 4 3/4" bi g-1.08 cu nd 15-20 culation 1% CaC12 CaC12 (19 ulate. d Cliffs	ft. shoe joint. w/2% KC1 water 2 + 8 #/sx. Gilsonit 5.7 ppg-1.18 cuft/sx based on new logs.
Estimated rate  14. I hereby certify that the foregoi	ng is true and correct	UUU PSI.	1			
Name (Printed/Typed)			Title Regu	latory Tec	chnician	
Terrye D. Bry	ant		Date			
Signature / Skull /	(Bryank)		_ <del></del>	ember 23,		
- / /	THIS SPACE	FOR FEDER	AL OR STAT	TE OFFICE US	SE	
Approved by S/ Duane W.	Spencer		Title			PSEP 29 1998
Conditions of approval, if any, are certify that the applicant holds leg which would entitle the applicant to	e attached. Approval of this not	ice does not wa hts in the subje	rrant or Office			
						La third States any false fictitious

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Form 3160-5

Louis Dreyfus Natural Gas Corp.
MKL Well No. 14
Notice of Intent to Acidize, Fracture Treat continued
September 23, 1998

and wait for balls to fall below perfs. Frac PC via 4" casing @ 60 BPM and  $\pm$  2,600 psi surface treating pressure. Pump  $\pm$  50,000 gallons 70 Quality N2 foam (20# XL base) and  $\pm$  90,000# 20/40 Arizona Sand and 10,000# 20/40 RCS.

- 8. RIH w/2 3/8" tubing & CO to TD w/N2. POOH w/tubing.
- 9. PU TA & RIH w/2 3/8" production tubing. PU & RIH w/3/4" rod string and 1 1/4" BHP. RDMO WOU. Build pad and install pumping unit. Hang well on.
- 10. Install wellhead compressor. Turn well to sales.

Anticipate work beginning 9/24/98.