



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor

Jennifer A. Salisbury

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

September 28, 2000

Mike Rainwater
Louis Dreyfus Nat. Gas Corp.
Po Box 220
Flora Vista NM 87415

RE: MKL #5, B, 06-26N-07W, API# 30-039-06727

Dear Mr. Rainwater:

The Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before November 15, 2000.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely,

A handwritten signature in cursive script that reads "Charlie T. Perrin".

Charlie T Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

XC: BLM Farmington
CTP File
Well File