

*well file*

GOVERNOR  
DAVID F. CARGO  
CHAIRMAN

State of New Mexico  
**Oil Conservation Commission**



LAND COMMISSIONER  
GUYTON B. HAYS  
MEMBER

1000 RIO BRAZOS ROAD  
AZTEC

STATE GEOLOGIST  
A. L. PORTER, JR.  
SECRETARY - DIRECTOR

August 19, 1968

Mr. Eric Nelson  
Marathon Oil Company  
1804 Brenwood Drive  
Farmington, New Mexico 87401

Re: Marathon Oil Company  
Jicarilla Apache #11  
M-28-26N-5W

Dear Mr. Nelson:

The packer-leakage test report for the referenced well does not prove zone separation.

Please cause the well to be retested as follows: Shut-in both zones for seven days or one test period, then produce the Pictured Cliffs zone into the pipeline for seven days while the Dakota zone remains shut-in. Measure pressures on both zones immediately prior to the Pictured Cliffs production, twice during the production period and at the end of the production period.

The test results can be attached to the reports on file.

If there are questions, please contact us.

Yours very truly,

*A. R. Kendrick*

A. R. Kendrick  
Engineer, District #3

ARK:mc

*Just received 10-24-68*  
*all*