Form 3160-5 (November 1994)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135 Expires July 31, 1996

5. Lease Serial No.

## Tract 251. Contract 154

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
shandoned well. Use Form 3160-3 (APD) for such proposals	_

6. If Indian, Allottee or Tribe Name

	DO ACT - 2 AM W: 53' amo ero as	Jicarilla Apache
SUBMIT IN TRIPLICATE -	Other instructions on reverse side	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well Oil X Gas Well Other  2. Name of Operator Marathon 011 Company  3a. Address P.O. Box 2490, Hobbs, NM 88245  4. Location of Well (Footage, Sec., T., R., M., or Surve) Descrip UL. A. Sec. 33, T-26-N, R-5-W 800' FNL & 800' FEL	OCT 2000 St. Phone No. (include area code) 505 / 393-7106	8. Well Name and No. Jicarilla Apache No. 12 DHC No. 2786  9. API Well No. 30-039-20002  10. Field and Pool, or Exploratory Area Jicarilla MV & BD Otero Chacra  11. County or Parish, State
12. CHECK APPROPRI	ATE BOX(ES) TO INDICATE NATURE OF NOTICE, I	
TYPE OF SUBMISSION	TYPE OF A	ACTION
Notice of Intent	Acidize Deepen	Production (Start/Resume) Water Shut-Off
X Subsequent Report		Reclamation Well Integrity  Recomplete X Other
Final Abandonment Notice		Temporarily Abandon RC Chacra and Water Disposal DHC

- 13 Describe Proposed or Commpleted Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonnent Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)
  - 7/19 RU pulling unit. ND wellhead. NU BOP. POOH w/tbg. RIH w/CIBP, set at 5075', POOH. Test. OK.
  - 7/20 Add perfs to Mesa Verde at 4700, 28, 77, 92, 4801, 21, 23, 46, 66, 4900, 03, 19, 23, 65, 92, 5003. 07, 13, 33 w/1 SPF.
  - 7/22 Acidize Mesa Verde w/1000 gals 15% acid.
  - 7/23 Frac Mesa Verde w/74,892 gals frac fluid containing 45,400# sand. RIH w/composite bridge plug, set at 3900'. Test, OK. Perf Chacra formation 3776-3803' w/2 SPF. Acidize w/1000 gals 10% acid. Frac w/35,413 gals 70Q N2 foam containing 81,300# sand. Open well.
  - 7/26 RIH w/bit, tag sand at 3800'. Clean out to top of plug and DO composite plug. Clean out to CIBP. DO CIBP at 5075'. RIH, tag btm at 7264'. Clean out to PBTD 7350'. POOH w/bit. RIH w/2 3/8" tbg. ND BOP. NU wellhead. Swab.
  - 8/1 RD pulling unit.

SN at 7228' Btm of tbg 7230'

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Kelly Cook	Title Records Processor	
Leeles Cook	Date 9/22/00	
THIS SPACE I	FOR FEDERAL OR STATE OFFICE USE	
Approved by	Lands and Mineral Hesources	OCT 0 & 2000
Conditions of approval, if any, are attached. Approval of this notice certify that the applicant holds legal or equitable title to those rights which would entitle the applicant to conduct operations thereon.	does not warrant or Office	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.