

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
MERIDIAN OIL

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
990' FNL, 990' FWL, Sec. 1, T-26-N, R-3-W, NMPM

RECEIVED
AUG 19 1996

OIL CON. DIV.
DIST. 3

5. Lease Number
Jic Contract 96
6. If Indian, All. or
Tribe Name
Jicarilla Apache
7. Unit Agreement Name
8. Well Name & Number
Jicarilla 96 #11
9. API Well No.
30-039-20171
10. Field and Pool
Gavilan Pictured Cliffs
11. County and State
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other -	

13. Describe Proposed or Completed Operations

7-25-96 MIRU. ND WH. NU BOP. TOO H w/tbg. TIH w/CIBP, set @ 3630'. PT csg, failed. TOO H. TIH, Plug #1: pump 6 sx Class "B" cmt on top of CIBP. TOO H to 3500', reverse circ hole clean. TOO H. SDON.

7-26-96 TIH, perf 2 sqz holes @ 3480'. TOO H. Establish injection. TIH w/cmt retainer, set @ 3440'. TOO H. TIH, attempt to establish injection. (Verbal approval to change plans from Robert Kent, BLM). Plug #2: pump 5 sx Class "B" cmt on top of cmt retainer @ 3315-3440'. TOO H to 2637'. Perf 3 sqz holes @ 2637'. TOO H. TIH w/cmt retainer, set @ 2587'. TOO H. TIH. Plug #3: pump 27 sx Class "B" cmt below cmt retainer, pump 4 sx Class "B" cmt on top of cmt retainer. TOO H. TIH perf 2 sqz holes @ 314'. TOO H. Establish circ down csg & out bradenhead. Plug #4: pump 84 sx Class "B" cmt down csg & out bradenhead. Circ 1 bbl cmt to surface. SD.

8-5-96 ND BOP. Cut off WH. Install dry hole marker w/10 sx Class "B" cmt. RD. Rig released. Well plugged and abandoned 8-5-96.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 8/9/96

(This space for Federal or State Office use)

APPROVED BY [Signature] Title Chief, Lands and Mineral Resources

CONDITION OF APPROVAL, if any:

AUG 16 1996