

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Jerome P. McHugh

3. Address and Telephone No.

650 S. Cherry St., Ste 1225, Denver, CO 80222

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

790' FSL 1850 FEL, Sec 16, T26N, R3W

5. Lease Designation and Serial No.

Contract 116

6. If Indian, Allottee or Tribe Name

Ticarilla

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Tribal #5

9. API Well No.

10. Field and Pool, or Exploratory Area

Basin Dakota

11. County or Parish, State

Rio Arriba, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☒ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to change this well to long term shut-in status.
This well has been reviewed and it is believed the well would be productive if pumping equipment were installed to lift water. Current economics make it unfeasible to install such equipment at the present time. It is requested this well be approved for long term shut-in status for the following reasons:

1. The well is currently unable to buck line pressure.
2. The well is unable to produce in paying quantities under current market conditions.
3. The well has additional reserves and has the potential to produce again if market conditions and/or line pressures change, or if pumping equipment can be economically installed.

APPROVAL EXPIRES

SEP 01 1992

14. I hereby certify that the foregoing is true and correct

Gary J. Johnson

Signed

Title

V.P. Engineering

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

APPROVED

3 Sept 1991

Date

Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See instruction on Reverse Side