UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 03733
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
	Breech
1. oil gas 💢 other	9. WELL NO.
2. NAME OF OPERATOR Caulkins Oil Company	258 10. FIELD OR WILDCAT NAME Otero Chacra,
3. ADDRESS OF OPERATOR	South Blanco Pictured Cliffs
P.O. Box 780 Farmington, New Mexico	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Section 18 26 North 6 West
below.) AT SURFACE: 1450' F/N & 1850' F/W	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same	Rio Arriba New Mexico
AT TOTAL DEPTH: Same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
,	6204' Gr.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	Service Control of the Control of th
FRACTURE TREAT SHOOT OR ACIDIZE	
REPAIR WELL PULL OR ALTER CASING MAY 1 198	(NOTE: Report results of multiple completion or zone
	change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES FARMING TON, N. M.	WASA STATES
(other)	<u> </u>
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is different measured and true vertical depths for all markers and zones pertinent	firectionally arilled, give subsurface locations and
11 . 11 . 1	mp 220/1 11
It is proposed to pull tubing, clean out to tubing and rerun used tubing.	TD 3384 , repair leak in
The estimated starting date is May 24, 1982.	
No new surface to be disturbed.	f specific
	La Maria
a to the Male of Manage and Toma	Set @ Ft.
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct	5-06-82
SIGNED Superintender	DATE J-00-04
APPROVIDE OF Federal or State of	
CONDITIONS OF APPROVAL AT ANY 0 1987	DATE
For JAMES E SIMS	

*See Instructions on Reverse Side

DISTRICT ENGINEER