

J

30-039-21853

F. Loc. 1850/S; 1710/W Elev. 7175 GL Spd. 8-13-78 Comp. 6-14-79 TD 6526 PB 82105
 Casing S. 10 3/4 @ 187 W 2.50 Sx. Int. 7 5/8 @ 4050 W 1.00 Sx. Pr. 5 1/2 @ 8397 W 4.00 Sx. T. 2 1/4 @ 7740
 Csg. Perf. 7537-7548 Prod. Stim. 3/24 @ 8275 to 8548
Surf

T
R
A
N
S

I.P. <u>248</u> MCF/D After <u>BOYD</u> Hrs. SICP <u> </u> PSI After <u> </u> Days GOR <u> </u> Grav. <u> </u> 1st Del. <u> </u>											
TOPS		NITDUAL <u>X</u>		Well Log <u>✓</u>		TEST DATA					
Kirtland		C-103	<u>X</u>	Plat	<u>X</u>	Schd.	PC	Q	PW	PD	Ref.No.
Fruitland		C-104	<u>X</u>	Electric Log	<u>XXX</u>						
Pictured Cliffs			<u>50</u>	C-122							
Cliff House	<u>5150</u>	Ditr		Dfa							
Menefee	<u>5690</u>	Datr		Dac							
Point Lookout	<u>6030</u>	<u>12/1/78 to 12/31/78</u> <u>8 1/2 @ 7537-7548 10000</u> <u>Surf</u>									
Mancos	<u>6150</u>										
Gallup											
Sanostee <u>Tecate</u>	<u>7535</u>										
Greenhorn											
Dakota	<u>8620</u>										
Morrison											
Entrada											
		<u>Superior</u>		<u>160</u>							

P
o

Wildhorse Gap RAs 24 T 26N R 4W U K Oper. So. Union Expl. Co. Lsg. Jicarilla A No. 22Y