

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

6. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1825' FSL, 1190' FWL, Sec.1, T-26-N, R-4-W, NMPM

5. Lease Number

Jic Contract 101

6. If Indian, All. or
Tribe Name

Jicarilla Apache

7. Unit Agreement Name

8. Well Name & Number

Jicarilla 101 #6

API Well No.

30-039-22009

Field and Pool

Blanco Mesaverde

11. County and State

Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent	☒ Abandonment	☐ Change of Plans
☒ Subsequent Report	☐ Recompletion	☐ New Construction
☐ Final Abandonment	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut off
	☐ Altering Casing	☐ Conversion to Injection
	☐ Other -	

13. Describe Proposed or Completed Operations

11-25-98 MIRU. SD for holiday.

11-30-98 ND WH. NU BOP. TIH, tag up @ 6087'. TOO H w/192 jts 2 3/8" tbgs. TIH, circ hole clean. SDON.

12-1-98 Circ hole clean. TOO H. TIH w/4 1/2" RBP & pkr; set RBP @ 5493', set pkr @ 5463'. PT RBP to 1000 psi, OK. Reset pkr @ 3938'. PT lnr @ 3938-5493' to 1000 psi, OK. Dump sd on RBP. TOO H w/pkr. TIH w/7" pkr, set @ 3017'. PT 7" csg @ 3017-5493' to 1000 psi, OK. Reset pkr @ 2570'. PT 7" csg @ 2570-5493' to 1000 psi, OK. Reset pkr @ 1301'. PT 7" csg @ 1301-5493' to 1000 psi, OK. PT csg @ 0-1301' to 1000 psi, OK. SDON.

12-2-98 (Verbal approval to plug and abandon from David Sitzler, BLM). PT csg @ 1301-5493' to 1150 psi, OK. PT csg @ 0-1301' to 1120 psi, failed. TIH w/retrieving tool. Circ sd off RBP. Release RBP, TOO H. TIH w/CIBP, set @ 5495'. TOO H. TIH, perf 3 sqz holes @ 2183' & 3 sqz holes @ 268'. TOO H. TIH. SDON.

12-3-98 Load hole w/25 bbl 2% KCl wtr. Plug #1: pump 12 sx Class "B" neat cmt on top of CIBP @ 5392-5495'. TOO H to 4052'. Plug #2: pump 78 sx Class "B" neat cmt @ 3589-4052'. TOO H to 3189'. Plug #3: pump 29 sx Class "B" neat cmt @ 3089-3189'. TOO H. TIH w/7" cmt retainer, set @ 2133'. Unable to pump into sqz holes @ 2133'. (Verbal approval to change plans from David Sitzler, BLM). Plug #4: pump 30 sx Class "B" neat cmt on top of cmt retainer @ 2133'. TOO H. Establish circ down 7" csg & out bradenhead. Plug #5: pump 121 sx Class "B" neat cmt down csg & out bradenhead. Circ 1 bbl cmt to surface. ND BOP. Cut off WH. Install dry hole marker w/10 sx Class "B" neat cmt. RD. Rig released. Well plugged and abandoned 12-3-98.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 12/8/98

(This space for Federal or State Office use)

APPROVED BY [Signature] Title Lands and Mineral Resources Date JAN 15 1999

CONDITION OF APPROVAL, if any: