

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO B7410 (505) 334-617B

December 13, 1984

Mr. Cecil Bell Southern Union Exploration Co. P.O. Box 2179 Farmington, NM 87499

Re: Jicarilla A 10E G-23-26N-4W Jicarilla A 22E P-24-26N-4W

Dear Cecil:

The 1984 packer tests on the referenced wells were inconclusive in proving zone separation.

Please reschedule and retest the wells in such a manner as to prove zone separation. Shut both zones in for a minimum of 3 days. Blow the higher pressured zone to the atmosphere for as long as it takes to get a significant pressure drop. Advise this office at least 24 hours prior to tests, so we may provide a witness.

Yours truly,

Charles Gholson

Deputy Oil & Gas Inspector

cc: Well Files