.•	Budget Bureau No. 74-11-
· · · · · · · · · · · · · · · · · · ·	5. LEASE
Porm 9-331 Dec. 1973 UNITED STATES	
DEPARTMENT OF THE INTERIOR	SF079162 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
DEPARTMENT OF THE	w y
GEOLOGICAL SURVEY	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS To proposals to drill or to deepen or plug back to a different	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
SUNDRY NOTICES AND REPORTS ON The Sundry Notices and Reports of the Sundry Notices and Su	8. FARM OR LEASE NAME
(Do not use this form for proposals to drill or to despression.) reservoir. Use Form 9–331–C for such proposals.)	Burns Federal
reservoir. Use Form 3-300	9. WELL NO.
1. oil gas well other	10. FIELD OR WILDCAT NAME
well	Basin Dakota
2. NAME OF OPERATOR	Basin Dakota 11. SEC., T., R., M., OR BLK. AND SURVEY OR
DEPCO, Inc. 3. ADDRESS OF OPERATOR Bldg-Denver, CO 80202	
3. ADDRESS OF OPERATOR 1000 Petroleum BldgDenver, CO 80202 1000 Petroleum BldgDenver, CO 80202 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1	Sec. 5-T26N-R7W
1 LOCATION OF WELL (REPORT LOCATION SEE	Sec. 5-120N 13. STATE 12. COUNTY OR PARISH 13. STATE New Mexico
4. LOCATION OF WELL (NEW SEW) below.) AT SURFACE: 1490' FSL, 730' FEL (NEW SEW) AT SURFACE: NEW SEW) INTERVAL: Same	R10 AIII2
AT SURFACE: 1490 FSD7	14 API NO.
AT SURFACE. 1430 AT TOP PROD. INTERVAL: Same	
AT TOP PROD. AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE 17. CHECK APPROPRIATE DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
16. CHECK APPROPRIATE DATA REPORT, OR OTHER DATA	6067 GR
REPORT, OR OF:	
REQUEST FOR APPROVAL TO:	1
TEST WATER SHUT-OFF	Winte completion or zone
COACTURE INCO	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
SHOOT OR ACIDIZE	change
	사는 사업 이 기가 사용하고 그를 특히 가는 활기
PULL OR ALTER CASING	o e e
CHANGE ZONES U. S. OF	NEOCICAL CHRYSY () E.S. () E.S. () E.S. ()
ABANDON* Back Pressure Test	tizent details, and give pertinent dates,
(other) Initial Day	ly state all pertinent
CHANGE ZONES ABANDON* (other) Initial Back Pressure Test 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clear including estimated date of starting any proposed work. If we including estimated date of starting any proposed work and zones in measured and true vertical depths for all markers and zones in the control of	pertinent to this work.)*
including estimated date of status for all markers and zone	
Weapong and	test 2" x 3/4
10-13-80 Dakota 7D SITP - 1752 psig. x 3 hr, FTP 48 psig, Q - 74	Back Plessur. AOF 755 MCF/D.
10-13-80 Dakota 7D S111	7 MCF/D, AO
A -	armb = 100 PP#7 "Self # All S. A.
x 3 hr, FTP 48 psig, y x 3 hr, FTP 48 psig, y 10-20-80 Mesaverde 7D SICP - 1100 ps pressure test 2" x 3/4" x 3 pressure test 2" x 3/4" x 3	FCP - 470 psig, FTP
10-20-80 Mesaverde 75 2" x 3/4" x	MCF/D. 6700
10-20-80 Mesave test 2" x 3/4 x pressure test	MCF/D.
Ö = 1134 11027	DIE COM
	2
	Set @
Subsurface Safety Valve: Manu. and Type	
Subsurface Safety valve. The Subsurface Safet	Supt. DATE 10/31/80
18. I hereby certify that the foregoing is true and control Production	
SIGNED This space for Feder	ral or State office use)
(This space for roots	DATE DATE DE DE CESTO
TITLE	masa Subbs Subs Subs Subs Subs Subs Subs Sub
APPROVED BY	
CONDITIONS OF ALL HOUSE	tribite the country of the country o
	*

*See Instructions on Reverse Side