



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

TONY ANAYA
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

December 13, 1984

Mr. Cecil Bell
Southern Union Exploration Co.
P.O. Box 2179
Farmington, NM 87499

Re: Jicarilla A 10E G-23-26N-4W
Jicarilla A 22E P-24-26N-4W

Dear Cecil:

The 1984 packer tests on the referenced wells were inconclusive in proving zone separation.

Please reschedule and retest the wells in such a manner as to prove zone separation. Shut both zones in for a minimum of 3 days. Blow the higher pressured zone to the atmosphere for as long as it takes to get a significant pressure drop. Advise this office at least 24 hours prior to tests, so we may provide a witness.

Yours truly,

A handwritten signature in cursive script, appearing to read "Charles Gholson".

Charles Gholson
Deputy Oil & Gas Inspector

cc: Well Files ✓