



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

GARREY CARRUTHERS
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

December 3, 1987

Mr. John Rector
Union Texas Petroleum Corp.
375 US Highway 64
Farmington, NM 87401

Re: Jicarilla G # 8 G-02-26N-5W
Jicarilla J #23 A-25-26N-5W

Dear John:

Packer leakage retests on the referenced wells indicated the G-8 has a packer or tubing leak.

In order to comply with Rule 112-A and the order authorizing the multiple completion, you are hereby directed to initiate immediate remedial activity. The J-23 was ok.

Yours truly,

A handwritten signature in cursive script, reading "Charles Gholson".

Charles Gholson
Deputy Oil & Gas Inspector

CG/dj

xc: Well Files
Operator File