Form 3160-5 (November 1983) (Formerly 9-331)

## UNITED STATES SUBMIT IN TRIPLICATE\* (Other instructions on reverse side)

Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985

5.	LEASE	DESIGNA	TION	THD	SERIA	L NO.
J	icar	illa	Cor	ntr	act	153

Formerly 9-	331)		U OF LAND M	ANAGEMENT	RECEIV		licarilla Con		
		DUKEA	O OI LAITO	DEDORTS O			IF INDIAN, ALLOTTER	OR TRIBE NAME	
	SUNDR	Y NOT	CES AND	KEPOK 12 O	N WELLS MAIL	k. /			
(Do n	ot use this for	o for propor	als to drill or to TION FOR PERM	IL— tot sacp bio		M 10: 14 17.	<u>Jicar</u> illa Ap		
					01 JUN 24 A	.2.	UNIT AGREEMENT NA	43	
OIL	GAS XX	OTHER			FARMINGTON RES	OURCE ARE	A N/A		
2. NAME OF	,	ULAND			EARMINGTON, M	W MEXICO		E	
Z. NIME OF C	Texas Pe	troleum			1 Million and		JICARILLA	J	
3. ADDRESS O						9.	WBLL NO.		
27 5 11	S Hichu	lav 64.	Farmington	, New Mexic	o 87401		10E		
	OF WELL (Repo	rt location o	learly and in acco	rdance with any S	tate requirements.	19	PIBLE AND POOL, OF	WILDCAT	
See also s	bace in nerow.	•				1 1	Blanco MV/Bas	<u> 1 N. UK</u>	
At suite	•					1:	1. SEC., T., B., M., OR B SURVEY OR AREA	LE. AND	
	925' FSL	£ 16581	FWI						
	923 136	d 1030	1 N C			· · · · · · · · · · · · · · · · · · ·	Section 26-T2		
14. PERMIT N	0		15. ELEVATIONS	(Show whether DF.	RT, GR, etc.)	1	2. COUNTY OR PARISE		
14. PERMIT	0.		6571'	G.L.		1 1	Rio Arriba	I NM	
				- · · · · · · · · · · · · · · · · · · ·	ature of Notice, Rep	O.L	or Data		
16.		Check A							
	NOT	ICE OF INTE	NTION TO:			SUBSEQUEN	SUBSEQUENT REPORT OF:		
			PULL OR ALTER C	ASING	WATER SHUT-OFF		REPAIRING T	WELL	
	ATER SHUT-OFF		MULTIPLE COMPLE	-	FRACTURE TREATM	ENT	ALTERING C	ASING	
FRACTUB			ABANDON*		SHOOTING OR ACIE	IZING	ABANDONME	NT.	
	R ACIDIZE		CHANGE PLANS		(Other)				
REPAIR	n 1	the and	a amminala	X	Completion	or Recountiell	multiple completion on Report and Log fo	rui. į	
(Other)	Recomp	ete anu	commingle	state all pertinen	details, and give perti- tions and measured and	nent dates, in	cluding estimated da	te of starting an	
17. DESCRIBE propos	PROPUSED OR C	ell is direct	ionally drilled, giv	e subsurface locat	ions and measured and	true vertical	depths for all marker	# FIRS Somes ber	
nent to	this work.) •								
م غراد	. Tausa	Dotnolo	um docinos	to recomple	ete this well i	n the Ta	pacito Gallur	)	
Unic	on rexas	retroret a with i	the Plance	Mos averde	and Basin Dakot	a pool.	The N.M.O.C.	D.	
and	Comming i	e with	me blanco	Order No. 1	R-7507 dated Ap	ril 20.	1984. A C-10	02	
n as	approved	the co	mmingiing:	order No. /	ated to the Gal	lun Th	e commingling	n	
15 6	attachea	indicat	ing the act	eage dedica	iced to the dar	1αρ	c comming in	9	
wil	l be comp	leted a	s follows:						
	C + DD -	+ 7100L	. inalatina	Dakota zo	20				
1.	Set BP a	t /100.	+ isolating	j Dakota zoi	Squeeze if ne	c essarv.			
2.	Run GK-C	UL-UBL	over dallup	)	,71',73',82', 6	anzi ngi	13' 30' 49'	.581.	
3.	Perforat	e Gallu	p With 1 3F	'r al 0309 1 221 oct o	,/1 ,/3 ,OZ , O	6708	30 ,30 ,73 80 S	, ,	
	05',86',	95 <b>,</b> 65	U9',II',I3'	,33,65,99, 4 UCl and E	3', 6606',17',	ealers	,000 ,70 ,00	-	
4.	Acidize	with 24	ou gais 157	onci dila o	0 - 7/8" ball s	linkad n	alled water		
5.	Frac wit	u 100,0	UU# 4U/4U S	ana iii /0,	000 gals 20# x-	· i i i k Eu	) le		
6.	Drill ou							G. Vess	
7.	Clean up	well.		71.001		Li.		***	
8.			# tubing to	) \100. <del>+</del> •			<i>H</i> : .	* · ·	
9.	Resume p	roducti	on.				- 40:1 10 1.187	7 - 1	
						O			
							" was in the	14.8	
						5 44	. Dist of	The state of the s	
						•	TING STATE OF THE	in Strain Contract to the Strain Contract to	

18. A hereby certify that the foregoing is true and correct 06/23/1987 Permit Coordinator TITLE . (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY: COMMISSION OF THE RESERVE

\*See Instructions on Reverse Side

## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

## OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

OK Elb

Form C-102 Revised 10-1-78

All distances must be from the outer boundaries of the Section. Well No. Operator <u>Jicarilla</u> 10 - EUnion Texas Petroleum County Township Range. Unit Letter Rio Arriba 5 West 26 North 26 Actual Fastage Location of Well: 1658 West South 925 feet from the line line and feet from the Dedicated Acreage: Pool Producing Formation Gallup Ground Level Elev. Tapacito Blanco Basin · Mesaverde Dakota 6571 1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below. S/2.5W/4 2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty). 3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling. etc? If answer is "yes," type of consolidation \_ Yes If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.). No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Division. CERTIFICATION Mesaverde I hereby certify that the Information con-Dakota tained herein is true and complete to the my knowledge and belief. Robert C. Fra<u>nk</u> Gallup Permit Coordina<u>tor</u> Jnion Texas Petroleum June 22, 1987 I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or er my supervision, and that the same Is true and correct to the best owledge and belief. Ori<u>ginal</u> signed 2/6/8 Date Surveyed Registered Professional Engineer and/or Land Surveyor . Certificate No.

2310

2000