

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☒ Drilling
well well
2. NAME OF OPERATOR
Marathon Oil Company
3. ADDRESS OF OPERATOR
P.O. Box 2659 Casper, WY 82602
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1,350' FNL & 1,625' FWL Unit F
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON ☐

(other) Please see below

SUBSEQUENT REPORT OF:

APR 24 1983
U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

(NOTE: Report results of multiple completion or zone change on Form 9-331-C)

5. LEASE
Contract 154
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Jicarilla Apache
9. WELL NO.
14E
10. FIELD OR WILDCAT NAME
Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 34, T26N., R5W
12. COUNTY OR PARISH, 13. STATE
Rio Arriba New Mexico
14. API NO.
30-039-22591
15. ELEVATIONS (SHOW DF, KDB, AND WD)
.6,566' GL, 6,579' KB

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

PROGRESS REPORT

See Attachments

From: 3-5-83 To: 3-17-83

Subsurface Safety Valve: Manu. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct.

SIGNED

W. E. Kugler

Drilling

SUPERINTENDENT

DATE

3-18-83

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY

ACCEPTED FOR RECORD

*See instructions on Reverse Side

APR 15 1983

NMOCC

FARMINGTON DISTRICT

BY

RLC

JICARILLA APACHE #14E

3-5-83 OPENED TBG TO PIT. DID NOT UNLOAD.

3-6-83/

3-11-83 SI.

3-12-83 RU ON WELL TO PULL SEPARATION SLEEVE SEATED IN SLIDING SLEEVE. RIH W/EQUALIZING PROBE. SEP SLEEVE CAME LOOSE & BLEW UP HOLE 20'. WIRELINE PARTED @ SURFACE WHILE JARRING ON SLEEVE.

3-13-83 TRYING TO RETRIEVE SEP SLEEVE.

3-14-83 RAN GRAPPLE, FISHED AS MUCH WIRELINE AS POSSIBLE. ABLE TO JAR SEP SLEEVE UP & DOWN HOLE 20'.

3-15-83 WIRELINE SERVICE FISHED REMAINING WIRELINE OUT OF TBG. PULLED SEP SLEEVE & CLOSE SLIDING SLEEVE.

3-16-83/

3-17-83 SI.