UNITED STATES DEPARTMENT OF THE INTERIOR		5. Lease / NMNM-03554	
BUREAU OF LAND MANAGEMENT		6. If Indian, Allottee or	Taka Nama
SUNDRY NOTICES AND REPORTS ON WELLS		7. Unit Agreement Name	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals)		7. Olde Agreement Pain	
1. Oil Well [] Gas Well [] Other []		8. Well Name and No.	
GAS WELL		BREECH "C" 689-M	
2. Name of Operator:		9. API Well No.	
Caulkins Oil Company 3. Address of Operator: (505) 622 1544		30-039-22669-00C1 10. Field and Pool, Exploratory Area	
(505) 632-1544		· ·	
P.O. Box 340, Bloomfield, NM 87413 4. Location of Well (Footage, Sec., Twp., Rge.)		DAKOTA, MESA VERDE  11. Country or Parish, State	
920' F/S 1100' F/E SEC. 12-26N-6W Rio Arriba Co., New Mexico  12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
TYPE OF SUBMISSION TYPE OF ACTION			
Notice of Intent	[] Abandonment	ı	Change of Plans
[ ] Notice of finein	[X]Recompletion	-	New Construction
[X] Subsequent Report	[X] Plugging Back	L	Non-Routine Fracturing
	[ ] Casing Repair	[	] Water Shut-Off
[ ] Final Abandonment Notice	[ ] Altering Casing	[	] Conversion to Injection
[ ] Other			] Dispose Water
17. Describe Proposed of Completed Operations:			
9/17/02 Rigged up.		13 15 18	1770
T. O. H. with 2 3/8" tubing.			
T. I. H. with 5 1/2" cement retainer on 2 3/8" tubing.		nn= 20	02
Set retainer at 7305'.			
Pulled out of retainer – loaded hole.			
Stung into retainer.		en e	
Plugged Dakota perforation with 110 sacks (129.80) class G neat.			
Pulled out of retainer.			
Displaced 150' of cement from top of retainer, 7305' to 7155'.			
Pulled 3 stands – reversed cement out of tubing.			
T. O. H. with 2 3/8" tubing.			<i>i ;</i>
(continued on page 2)			
	(continued on page 2)		•
			22
NOTE: The format is issued in lieu of U.S. BLM Form 3160-5			
18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT			22 To 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
SIGNED: Ment J Vergue TITLE: Superintendent DATE: September 30, 2002			
ROBERT L. VERQUER		·	FARISINGTON FIELD DEVIDE
APPROVED BY:	TITLE:	_ DATE:	all the second
CONDITIONS OF APPROVAL, IF ANY			

NMOCD

Caulkins Oil Company BLM Sundry Notice Breech "C" 689-M September 30, 2002 Page 2

9-18-02 Logged and perforated Tocito zone.

Perforations – 4 shots per foot from  $6940^{\circ} - 6950^{\circ}$  and  $6831^{\circ} - 6837^{\circ}$ .

T. I. H. with fullbore packer on 2 7/8" tubing.

Set packer at 5680'.

Tested tubing and casing - OK.

Recovered standing valve.

9-19-02 Rigged up Schlumberger.

 $N^2$  foam frac'd Tocito formation with 37,530# 20/40 sand, 788 (Mscf)  $N^2$  and 15,899 gallons fluid.

Shut well in.

9-20-02 2450# on tubing this morning.

Flowed well back through 1/2" choke for 4 hours.

Released packer, T. O. H. laying down 2 7/8" tubing.

T. I. H. with 2 3/8" production tubing.

9-23-02 Tagged sand at 7050'.

Cleaned out to 7150'.

Landed tubing on doughnut at 6944'.

Rigged down and moved.

Well now completed as a single Tocito well.

