

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Curtis J. Little Oil and Gas

3. Address and Telephone No.

P.O. Box 1258, Farmington, NM 87499

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

890' FNL and 1620' FEL Sec. 4 T25N R7W

5. Lease Designation and Serial No.
NM-011639

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Grevey #2

9. API Well No.

30-039-22788

10. Field and Pool, or Exploratory Area

Ballard PC

11. County or Parish, State

Rio Arriba, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10-26-95 Safety Meeting. Road rig and equipment to sand wash across from location. Wait for blade to tow equipment across wash. Wait for front end loader to tow equipment across wash. Rig up and equipment. No casing or tubing psi. ND wellhead. NU BOP and test. Layout relief lines to pit. Pump 3 bbls water to establish circulation. Pump additional 10 bbls water. Plug #1 with 30 sxs Class B cement from 2264' to 1174' to cover Pictured Cliffs perforations and over Ojo Alamo top. POH and LD 30 joints 1-1/4" tubing, standing back 39 joints tubing. Total of 69 joints 1-1/4" tubing from well (2190'). Shut in well and WOC overnight. SDFD. 10-27-95 RIH with 1-1/4" tubing; tag cement at 1608'. below Ojo Alamo top. Cement had fallen back. POH to 1588'. Pump 4 bbls water to establish rate into bradenhead valve 2bpm to 100#. Psi. test casing to 1000#, held O.K. Plug #2 with 15sxs Class B cement inside casing from 1588' to 1043' over Ojo Alamo top. POH and LD tubing. Perforate 2 squeeze holes at 250'; bradenhead began flowing water. Establish circulation out bradenhead. Plug #3 with 62 sxs Class B cement down 2-7/8" casing from 250' to surface, circulate good cement out bradenhead. Shut in well and WOC. Open up well. ND BOP. Cut wellhead off. Mix 14 sxs Class B cement and install P&A marker. Rig down rig and equipment. Move off location.

14. I hereby certify that the foregoing is true and correct

Signed

Title Operator

Date 11-20-95

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

APPROVED

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

NMOCO

DISTRICT MANAGER