

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other
2. NAME OF OPERATOR
Tenneco Oil Company
3. ADDRESS OF OPERATOR
Box 3249, Englewood, CO 80155
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 870' FWL, 1850 FNL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

- | | |
|----------------------|--------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> |
| ABANDON* | <input type="checkbox"/> |
| (other) | <input type="checkbox"/> |

RECEIVED (NO

AUG 19 1982

U. S. DEPARTMENT OF AGRICULTURE
WASHINGTON, D. C.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8/3/82: MIRUSU. NDWH, NUBOP. Kill tbg. POOH w/same. RIH w/WL set retrievable BP set @ 7265'. Load hole w/1% KCL wtr. PT BP to 3500 psi. Dropped 2 sx sd on top of plug. RIH w/tbg. Spotted 500 gal. 7½% DI HCL @ 7205'. POOH w/tbg.

8/4/82: Perf'd Dakota A zone w/2 JSPF 7190-7201 (11', 22 holes). Brk dn formation @1800 psi, estab. rate @ 16 BPM & 1800 psi. Acidized & balled off w/400 gal 15% wtd acid & 33 1.1SG ball slrs. Ball off complete. Roundtripped junkbasket to 7260'. Frac'd A zone w/27,500 gal 30# X-L gel & 19,800# 20/40 SD. Well screened out when 3# SD hit formation.

8/5/82: RIH w/tbg & retrieving head. Tagged sd fill @ 4175'. CO to within 60' of RBP w/KCL wtr. CO last 60' with foam. Retrieved BP. POOH w/tbg & plug. RIH w/tbg, pmp out plug & sn, land @ 7350'. Kicked well around, left flwg.

8/8/82: Swbd 150 BF.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Kenneth Wilson TITLE Production Analyst DATE August 10, 1982

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE **ACCEPTED FOR RECORD**

AUG 25 1982

***See Instructions on Reverse Side**

FARMER:

RY

5m n

NMOCC