

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well ☐ gas ☒ well ☐ other

2. NAME OF OPERATOR
Supron Energy Corporation

3. ADDRESS OF OPERATOR
P.O. Box 808, Farmington, New Mexico 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: *790' f/South - 1120' f/West lines*
AT TOP PROD. INTERVAL: *Same as above*
AT TOTAL DEPTH: *Same as above*

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

5. LEASE
Contract No. 153

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jicarilla

9. WELL NO.
8-E

10. FIELD OR WILDCAT NAME
Blanco Mesaverde - Basin, Dakota

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA
Sec. 25, T26N, R5W, N.M.P.M.

12. COUNTY OR PARISH
Rio Arriba

13. STATE
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6664 Gr.

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☒

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

SUBSEQUENT REPORT OF:

☐ APPROVED

☐ JUL 2 1982

☐ REJECTED

☐ PENDING

☐ OTHER

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We desire to change the pipe and cement program as follows: Drill 12-1/4" surface hole using Gelex and water to T.D. of approximately 300 ft. Run new 9-5/8", 32.30#, H-40 casing to T.D. Cement with approximately 190 cu. ft. of cement circulated to the surface. Pressure test the casing. Drill out with a permaloid non-dispersed starch base mud to T.D. of approximately 7610 ft. Log the well. Run new 7", 23.00#, K-55 casing to T.D. with stage tools at approximately 5600 ft. and 2650 ft. Cement the first stage with approximately 410 cu. ft. of cement. Cement the 2nd stage with approximately 530 cu. ft. of cement. Cement the 3rd stage with approximately 830 cu. ft. of cement. Drill out the stage tools. Pressure test the casing. Perf and frac the Dakota formation. Set a bridge plug above the Dakota zone. Perf and frac the Mesaverde zone. Clean up the Mesaverde zone. Remove the bridge plug. Clean up the Dakota zone. Run 2-3/8", 4.7#, EUE, J-55 tubing with a production packer and set it above the Dakota zone. Run a second string of 2-3/8", 4.7#, EUE, J-55 tubing and land it in the Mesaverde zone. Nipple down the well head. Test the packer (over Subsurface Safety Valve: Manu. and type *Set @* Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *Rudy D. Motto* TITLE *Area Supt.* DATE *July 2, 1982*

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

NMOCC

JUL 7 1982

Elliott
DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and data well site conditioned for final inspection looking to approval of the abandonment.

for leakage. Test the Dakota zone. Test the Mesaverde zone. Connect to a Gathering System.

The gas from this well has previously been dedicated.

U.S. GPO : 1975 O - 214-149

Form Approved
October Bureau No. 40-11424

1. NAME OF OPERATOR
2. ADDRESS OF OPERATOR
3. LOCATION OF WELL (REPORT LOCATION OF EARLY SEE SPACE IN
4. SURFACE
5. TOP PROD. INTERVAL
6. TOTAL DEPTH
7. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE
8. REPORT OR OTHER DATA
9. REQUEST FOR APPROVAL TO
10. TEST WATER SHUT-OFF
11. PRODUCE TREAT
12. SHUT OR ACIDIZE
13. REPAIR WELL
14. ROLL OR ALTER CASING
15. MAKE THE COMPLETE
16. CHANGE SOUNDS
17. REMOVAL

18. ELEVATION
19. COUNTY OR
20. AREA
21. FIELD OR W
22. WELL NO.
23. FARM OR L
24. UNIT AGREED
25. INDIAN A
26. TRIBAL
27. LEASE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different
formation. Use Form G-331-C for such proposals.

1. ☐ Well
2. ☐ Well
3. ☐ Other

4. NAME OF OPERATOR
5. ADDRESS OF OPERATOR
6. LOCATION OF WELL (REPORT LOCATION OF EARLY SEE SPACE IN
7. SURFACE
8. TOP PROD. INTERVAL
9. TOTAL DEPTH
10. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE
11. REPORT OR OTHER DATA
12. REQUEST FOR APPROVAL TO
13. TEST WATER SHUT-OFF
14. PRODUCE TREAT
15. SHUT OR ACIDIZE
16. REPAIR WELL
17. ROLL OR ALTER CASING
18. MAKE THE COMPLETE
19. CHANGE SOUNDS
20. REMOVAL