

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. Contract No. 150	
2. NAME OF OPERATOR Union Texas Petroleum Corp.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache	
3. ADDRESS OF OPERATOR P.O. Box 1290, Farmington, NM 87499		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1710' FSL and 810' FEL		8. FARM OR LEASE NAME Jicarilla "G"	
14. PERMIT NO.		9. WELL NO. 8-E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6731 GR		10. FIELD AND POOL, OR WILDCAT Basin Dakota - B.S. Mesa Gall	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 2, T26N, R5W, NMPM	
		12. COUNTY OR PARISH Rio Arriba	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☒

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐  
☐

FRACTURE TREATMENT

REPAIRING WELL

SHOOTING OR ACIDIZING

ALTERING CASING

(Other)

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

We desire to change the completion of this well as follows:

After drilling out the D.V. tool and cleaning out to T.D. we desire to perforate and fracture and test the Dakota zone. Set a bridge plug above the Dakota zone and perforate, fracture and test the Gallup zone. Remove the bridge plug. Run one string of 2-3/8" J55 tubing to the Dakota zone and nipple down the wellhead. Test the well and connect to a gathering system as a commingled Gallup Dakota completion as approved by the State of New Mexico by hearing in Case No. 8185, Order No. 7539 on May 21, 1984.

RECEIVED

JUN 28 1984

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

OIL CO  
DIST. 5

18. I hereby certify that the foregoing is true and correct

SIGNED

Rudy D. Motto

TITLE Area Operations Manager

DATE June 22, 1984

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

NMOCC

\*See Instructions on Reverse Side

APPROVED

JUN 29 1984

DATE

AREA MANAGER  
FARMINGTON RESOURCE AREA