Form 3160-5 November 1983) Formerly 9-331) DEF	UNITED STATES SIINMIT IN TRIPLICATES (Other Instructions on re-			Budget Bureau No. 1004-0135 Expires August 31, 1985 5, LEARE DEDIGNATION AND MERIAL NO.
BUREAU OF LAND MANAGEMENT				SF 079035-A
SUNDRY (Do not use thin form form the "	NOTICES	AND REPORT	S ON WELLS  ug back to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
			CECEIVED	7. UNIT AGREEMENT NAME
WELL WELL X	TREE	0.1.0	UL 2 4 1985	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR	Caulkins	Oil Company	EAU OF LAND MANAGE E .	Breech "A"
	P.O. Box	780 Farmingto	on, New Mexico 87499	625-Е
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)				Otero Chacra
At surface				Basin Dakota - Blanco MV
1590' F/S and 1000' F/W				SURVEY OR ARMA
				Section 8, 26 North 6 West
14. PERMIT NO.	16.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6496 Gr.		Rio Arriba New Mexico
16. • Ch			e Nature of Notice, Report, or	
	eck Abbiob			QUENT REPORT OF:
	٦		fΣ	<u> </u>
TEST WATER SEUT-OFF	-	PLE COMPLETE	WATER SHUT-OFF PRACTURE TREATMENT	BEFAIRING WELL
SHOOT OR ACIDIES	ABANDO	1	BEOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANG	E PLANS	(Other) Spud and C	
(Other)	·		(Norx: Report resul Completion or Recom	ts of multiple completion on Well pletion Report and Log form.)
nent to this work.)	Spud 12		nole at 5:30 PM 7-19	Jeal depths for all markers and zones perti-
	Ran 10 joints 9 5/8" 36# H-36 Casing to 421' and cemented with 250 sacks (295 Cu.Ft.) Class "B" cement containing 2% CaCl and 1/4# Flocele per sack.  Plug down 4:45 PM 7-20-85.			
Cement circulated to surface.				
	Tested :	surface casing	with 1000# for 30 minu	ites. No decrease in pressure.
				BECEIVED
			•	JUL3 0 1985
2				OIL CON. DIV. DIST. 3
18. I hereby certify that the fo	regoing is true	And correct  Assiltante	Superintendent	7-23-85
(This space for Federal or	State office nec	)		
APPROVED BY		TITLE .		Marie Tab