

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

10:5053250328

PAGE 2/2

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Apache Corporation

3. Address and Telephone No.

2855 Southside River Rd. Suite A Farmington, NM.

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

505-325-0318

2260' FNL 1970' FWL SWNW Sec 35 T26N R3W

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

JAT A118

6. If Indian, Allottee or Tribe Name

Jicarilla Apache

7. If Unit or CA, Agreement Designation

8. Well Name and No.

A118 #13

9. API Well No.

3003923707

10. Field and Pool, or Exploratory Area

NE Ojito Gal/Dak

11. County or Parish, State

Rio Arriba, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☒ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

AFMSS

Adjud Amy
Engr
Geol
Surf
Appvl

☒ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on W Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Apache Corporation is moving in a P&A rig and services on this well on 11-26-01.

Apache proposes to plug and abandon the Gallup and Dakota according to Approved P&A Sundry dated 5-4-00, then test the Mesa Verde for production potential. The Mesa Verde will be perforated (perfs yet to be determined), acidized, and flow tested. If the well test shows no potential, the wellbore will be P&A'd, following the 5-4-00 procedures. If the well shows potential, the well will be fraced at a later date and the well will be returned to production as a Mesa Verde only.

14. I hereby certify that the foregoing is true and correct

Signed

Title Sr. Prod Foreman

Date 11-24-01

(This space for Federal or State office use)

Approved by

Title Lands and Mineral Resources

Date 12/17/01

Conditions of approval, if any: