

OIL CONSERVATION DIVISION

P. O. BOX 2088

Form C-102
Revised 10-1-78

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

SANTA FE, NEW MEXICO 87501

All distances must be from the outer boundaries of the Section.

Operator Dugan Production Corporation			Lease Tapacitos		Well No. 4
Unit Letter 0	Section 36	Township 26 North	Range 2 West	County Rio Arriba	
Actual Footage Location of Wells 1100 feet from the South line and 1600 feet from the East line					
Ground Level Elev. 7295	Producing Formation Dakota	Pool Basin Dakota	Dedicated Acreage: 320 Acres		

1. Outline the acreage dedicated to the subject well by colored pencil or hatchure marks on the plat below.
2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty).
3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling, etc?

☐ Yes ☐ No If answer is "yes," type of consolidation _____

If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.) _____

No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Division.

RECEIVED

NOV 29 1985

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

DEC 06 1985

OIL CON. DIV
DIST. 3

SEC. 36

1600'

50% Dugan Prpd.
30% Bob Andes
20% Earl Lang
1100

NM 7993

CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.

Jim L. Jacobs

Name
Jim L. Jacobs

Position
Geologist

Company
Dugan Production Corp.

Date
November 27, 1985

EDGAR L. RISENHOWER
NEW MEXICO
5979
I hereby certify that the well location is correct and that the same is based on actual surveys made by me or under my supervision, and that the same is correct to the best of my knowledge and belief.

Date Surveyed
September 2, 1985

Registered Professional Engineer
and/or Land Surveyor

Edgar L. Risenhower