

Divide #2

P-35-26N-2W

DUGAN PRODUCTION CORP.

F

30-049-23042

5-29-86

NSL-2255

F. loc. 990/S; 1200/E Elev. 7700 GL Spd. Comp. TD PB

Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @ T Gas
Csg. Perf. Prod. Stim.

I.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR Grav. 1st Del. Gas 1st Del. Oil

TOPS	NI TD X	Well Log	TEST DATA								Ref.No.
Ojo Alamo	C-103	Plat X	Schd.	PC	Q	PW	PD	D			
Kirtland	C-104	Electric Log									
Fruitland		C-122									
Pictured Cliffs	Ditr	Dfa									
Chacra	Datr	Dac									
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
		NSL-2255 Acres E/320									

P
o
o

I Gavil.Man. Co. RA S 35 T 26N R 2W U P Oper. Dugan Production Corp Lse. Divide No. 2

NM-28709 (WG)
3162.3-1.0 (019)

MAR 27 1990

CERTIFIED--RETURN RECEIPT REQUESTED
P-140-441-582

Dugan Production Corporation
P. O. Box 420
Farmington, NM 87499

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 2 Divide, 3E/4SE/4 sec. 35, T. 26 N., R. 2 W., Rio Arriba County, New Mexico, lease NM-28709. As discussed with Jim Jacobs of your company on March 19, 1990, the subject APD is rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 15 days, we will presume that no construction occurred. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely,

Don Thompson

FOR Ron Fellows
Area Manager

Enclosure

cc: New Mexico Oil Conservation Division, 310 Old Santa Fe Trail,
Room 206, Santa Fe, NM 87503

ABANDONED LOCATION

ABANDONED LOCATION