

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

Jicarilla Contract 107

6. If Indian, Allottee or Tribe Name

Jicarilla Apache

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Jicarilla 107 9

9. API Well No.

30-039-24212

10. Field and Pool, or Exploratory Area

W. Lindrith Gallup-Dakota
Blanco Mesaverde

11. County or Parish, State

Rio Arriba NM

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Energen Resources Corporation

3a. Address

2198 Bloomfield Highway, Farmington, NM 87401

3b. Phone No. (include area code)

505-325-6800

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1240' FSL, 710' FEL, Sec. 28, T26N, R4W, N.M.P.M.

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other

Downhole Commingle

Pay Add

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

06/06/02 - 06/17/02 MIRU. ND wellhead. NU BOP. TOH with 2-3/8" tubing. TIH with RBP, set @ 6304'. Test casing to 3000 psi. Ran GR-CCL-CBL from 5100' - 6100'. Perforate Point Lookout 5847'-6008'. Frac with 127,370 gals 60Q foam slickwater & 110,000# of 20/40 sand. TIH and clean out with air mist. TOH. TIH and retrieve RBP. Release RBP and TOH. Clean out to PBDT 8102' with air mist. TIH with 2-3/8" tubing, land @ 8029'. ND BOP & wellhead. RDMO. Return well to production.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Vicki Donaghey

Title

Production Assistant

Date 06/24/02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

/s/ Patricia M. Hester

Title Lands and Mineral Resources

Date

JUN 26 2002

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.