

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on reverse side)

LEASE DESIGNATION AND SERIAL

SF-079160

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.

WELL ☐ GAS WELL ☒ OTHER

NAME OF OPERATOR

Union Oil Company of California

ADDRESS OF OPERATOR

Box 671 - Midland, TX 79702

LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

1645' FNL & 1125' FEL

PERMIT NO.

ELEVATIONS (Show whether DF, RT, GR, etc.)

6523' GR

UNIT AGREEMENT NAME

Rincon Unit

FARM OR LEASE NAME

Rincon Unit

WELL NO.

295

FIELD AND POOL OR WILDCAT

Basin Fruitland Coal

SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 11 T. 26N. R. 7W

COUNTY OF PARISH, STATE

Rio Arriba NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

TEST OR TREAT

MULTIPLE COMPLETE

FRACURE TREATMENT

ALTERING CASING

DISPERSE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANT

(Other) Spud - run casing

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6/14 363' WOC. 363' 1/4. SD. 1" @ 363'. MUD: 8.7, 60, N.C., SPUD MUD. MIRU ARAPAHOE RIG #2, SPUT 12-1/4" HOLE @ 5:30 PM 6-14-90. TD 12-1/4" HOLE @ 363' @ 10:30 PM 6-14-90. CIRC 1/2 HR & TOH. R&C 7 JTS & 1 PC 348'. 8-5/8" 20# X-42 STC 3RD NEW SMLS CSG SET @ 361'. CMT W/ 300 SX CL "B" + 2% CACL2 + 1/4#/SK C.S. MIXED @ 15.6 PPG DISP W/21 BFW @ 3 BPM & 250 PDI. CIP & JC @ 1:30 AM 6-15-90. WOC INCOMPLETE @ 3-1/2 HRS. CIRC 140 SX CMT TO SURFACE.

6/15 1630' DRLG. 1267' 1/13. SD & SH. 1/2" @ 825, 3/4" @ 1380. MUD: 8.9, 31, 12, -, -, -. CONT'D WOC. CUT OFF 8-58" CSG WELD ON BRADENHEAD. NUBOP. P TEST BLIND RAMS, MANIFOLD & CSG TO 600 PSI FOR 30 MIN-OK. TIH & TAG CMT @ 320'. TEST PIPE RAMS TO 600 PSI FOR 30 MIN-OK. DRILL PLUG & CONT. DRLG NEW FORMATION @ 2:30 PM 6-15-90. TOTAL WOC: 13 HRS.

6/16 2569' TFB #3. 939' 1/19-1/2. SD & SH. 1" @ 1911, 1" @ 2410. MUD: 9.2, 45, 10, 1, 7-1/2, 400. DRLG, TFB #3 IN PROGRESS.

6/17 2800' CIRC FOR 2ND STAGE. 231/4-3/4. COAL, SD, SH. 1-1/4" @ 2800'. MUD: 9, 41, 8.6, 1, 7.5, 350. FINISH BIT TRIP & DRILL TO TD @ 2800' @ 1:00 PM 6-17-90. CIRC 1/2 HR & SHORT TRIP. CIRC 1-1/4 HR & TOH FOR LOGS. LOG W/ SDL, MRL & GR FROM 2792' (WLTD) - 361'. TIH & CIRC 1/4 HR. LDDP-DC'S. R&C 64 JTS & 1 PC 2786' 4-1/2" 11.6# J-55 LTC 8RD NEW SMLS CSG SET @ 2799' W/ DV TOOL @ 2362'. CIRC 1 HR & BATCH MIX CMT. CMT 1ST STAGE W/150 SX CL "H" + .9% FLOK + .18% THRIFTYLITE + 3#/SK HISEAL + 3% KCL MIXED @ 15.9 PPG. DISP W/10 BFW & 33 BBL MUD @ 4 BPM & 500 PSI. BUMP PLUG @ 1500 PSI - HELD. CIP @ 500 AM 6-18-90. CIRC FOR 2ND STG INCOMPLETE.

6/18 MORT. 4-1/2" CSG SET @ 2799'. DROP BOMB & OPEN DV TOOL. CIRC FOR 2ND STG @ 4 HRS. CMT 2ND STG W/500 SXS PSL + 8X CF1 + 3#/SX HI-SEAL + 1/4#/SX CS MIXED @ 12.6 PPG TAILED W/50 SXS CLASS "B", NEAT MIXED @ 15.6 PPG. DISPL W/37 BFW @ 4 BPM & 600 PSI. CLOSED DV TOOL @ 1850 PSI, OK. CIP & JC @ 10:15 PM 6-18-90. CIRC'D 40 SXS CMT ON 1ST STG TO SURFACE & 140 SX CMT TO SURFACE ON 2ND STG. ND BOP & SET SLIPS & CUT OFF 4-1/2" CSG. RIG REL @ 12:15 PM 6-18-90.

I hereby certify that the foregoing is true and correct

SIGNED

Charlotte Beeson

TITLE

Drlg. Clerk

DATE

6-19-90

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

DATE

JUL 09 1990

FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side

BY