

United States Department of the Interior

BUREAU OF LAND MANAGEMENT Farmington Resource Area

1235 Laplata Highway Farmington, New Mexico 87401



IN REPLY REFER TO SF-078571 et al. (WC) 3162.3-1 (019)

Union Oil Company of California P.O. Box 2074 Farmington, NM 87499

OCT. 1 0 1891

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- 1. 8 Day B, sec. 7, T. 27 N., R. 8 W., San Juan County, NM, lease SF-078571.
 - 2. 297 Rincon Unit, sec. 34, T. 27 N., R. 7 W., Rio Arriba County, NM, lease SF-080213.
 - 3. 302 Rincon Unit, sec. 25, T. 27 N., R. 7 W., Rio Arriba County, NM, lease SF-079321.
- 4. 299 Rincon Unit, sec. 6, T. 26 N., R. 6 W., Rio Arriba County, NM, lease SF-079301-A.

The subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

John L. Keller

Chief, Branch of Mineral Resources

4 Enclosures

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOCATION OCT21 1991
OIL CON. OIV
DIST. 3