

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

ENERGEN RESOURCES CORPORATION

3a. Address

2198 Bloomfield Highway, Farmington, NM 87401

3b. Phone No.

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1700' FNL, 800' FWL, Sec. 34, T26N, R3W, N.M.P.M.

Lease Serial No.

JIC CONT. 117

6. If Indian, Allottee or Tribe Name

Jicarilla Apache

7. If Unit or CA/Agreement, Name and/or N

8. Well Name and No.

Jicarilla 117E 3A

9. API Well No.

30-039-25964

10. Field and Pool, or Exploratory Area

Blanco MV/NE Ojito GL-DK

11. County or Parish, State

Rio Arriba NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other

Add PC

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

6/18/01 MIRU. ND wellhead, NU BOP. TOH with 2-3/8" tubing.

6/19/01 RU Halliburton wireline. RIH and set CIBP at 4300'. Test RBP to 3000 psi - OK. Perforate Pictured Cliffs from 4074'-4106' w/1 SPF, total 32 holes. RD Halliburton.

6/20/01 RU Halliburton. Frac Pictured Cliffs with 30,160 foamed gals of fluid and 56,437# 20/40 sand. RD Halliburton. Flow back on 1/4" choke.

6/21/01 Flow back on 1/4" choke.

6/22/01 TIH and clean out to CIBP at 4300'. Gauge well on 1/4" choke at 471 MCFPD. Drill out CIBP at 4300'. Continue TIH to 8400'.

6/25/01 TOH with workstring. TIH with 2-3/8" tubing, land at 8044', seating nipple at 8011'. Blow hole with air. ND BOP, NU wellhead. RDMO.

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Don Graham

Title

Drilling/Completion Foreman

Date 8/7/01

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

/s/ Brian W. Davis

Title Lands and Mineral Department

Date AUG 29 2001

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.