Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

Jicarilla Contract #117

New Construction

Water Shut-Off

Dispose Water

Non-Routine Fracturing

Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

SUNDRY NOTICES AND REPORTS Do not use this form for proposals to drill or to deepen or		6. If Indian, Allottee or Tribe Name
Use "APPLICATION FOR PERMIT - " for	r such proposals	Jicarilla Apache
SUBMIT IN TRIPLIC	7. If Unit or CA, Agreement Designation	
Type of Well Oil X Gas Well Other	- GEORIVER	8. Well Name and No. Jicarilla 117E 7A
Taurus Exploration U.S.A., Inc.	III FES 1 3 1999	9. API Well No.
2198 Bloomfield Highway, Farmington, NM 87401 Location of Well (Footage, Sec., T., R., M., or Survey Description)	WILL GRAND BUILD	30-039-25988 10. Field and Pool, or exploratory Area Tapacito Pictured Cliffs/
790 FSL, 1850 FEL, SEC. 28, T26N, R3W, N.M.P.M	. 946.3	Blanco Mesa Verde 11. County or Parish, State Rio Arriba NM
2. CHECK APPROPRIATE BOX(s) TO INDICA	TE NATURE OF NOTICE, REPORT	, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	Abandonment	Change of Plans

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Recompletion

Plugging Back

Casing Repair

Altering Casing

In reference to Jicarilla Contract 117 1310 (010) it is intended to attempt to circulate cement to surface on 7" casing string as follows: (Note circulation was lost during primary cement job.)

1. MIRU. TOH. Set RBP.

Subsequent Report

Final Abandonment Notice

- 2. Perforate squeeze holes at 2850'. Attempt to gain circulation to surface. If no circulation is established, squeeze cement with 150 sks Class "B". Run trmperature survey. WOC. Continue to find top and squeeze until cement covers Nacimiento at 2000'.
- 3. If circulation is established, cement to surface with 300 sks 3% econolite followed by 150 sks Class "B".
- 4. Drill out squeeze cement. Test casing to 1000 psi. Rerun production tubing.

14. I hereby cerufy that the foregoine is true and correct Signed	Title Production Superintendent	Date 1/25/99
(This space for Folieral or State of Folieral or State	Title Lands and Mineral Resources	FEB 1 1999 - Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.